




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 LIFE TDI
Colour	Silver
Year of manufacture	2015
Top speed	104 mph
0 - 60 mph	13.5 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	48.7 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-23
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-19
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	12
Total items failed	1

MOT #9	2023-10-11 14:14
MOT test number	286048410999
Result	✓ Passed
Next expiry date	2024-10-19

MOT #8	2022-10-18 13:16
MOT test number	260519908059
Result	✓ Passed

MOT #7	2021-10-20 13:28
MOT test number	615091570150
Result	✓ Passed

MOT #6	2020-07-20 11:40
MOT test number	122286806898
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front daytime running light not working



MOT #5	2020-07-20 11:40
MOT test number	139704991362
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
Advice	Offside Front daytime running light not working
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4	2019-07-19 14:16
MOT test number	302426752265
Result	✓ Passed

MOT #3	2019-07-19 08:59
MOT test number	609747381423
Result	✗ Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #2	2018-07-11 13:40
MOT test number	421678024327
Result	✓ Passed



MOT #1 2018-07-05 14:34

MOT test number 522014945198

Result ✗ Failed

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MAJOR Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Registration plate lamp likely to become detached (4.7.1 (c) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
19 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YW15ATF
Plate since	2015-03-29
Current registration	YW15ATF
Plate since	2015-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-08
Last registration	2023-10-11
Complete history	See info



Registration #1	2015-07-08	7 mi
Registration #2	2018-07-05	25.058 mi
Registration #3	2018-07-11	25.131 mi
Registration #4	2019-07-19	32.274 mi
Registration #5	2019-07-19	32.276 mi
Registration #6	2020-07-20	37.366 mi
Registration #7	2023-10-11	37.366 mi
Registration #8	2023-10-11	37.366 mi
Registration #9	2023-10-11	37.366 mi
Registration #10	2023-10-11	37.366 mi
Registration #11	2023-10-11	37.366 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1861 mm
Length	4876 mm
Kerb weight	1769 kg
Max. allowed weight	2365 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAYDAP1174