



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO MULTIJET EASY
Colour	Blue
Year of manufacture	2015
Top speed	102 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-29
Pictures	6
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-20
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	32
Total items failed	6

MOT #7	2024-03-21 16:47
MOT test number	491345812290
Result	✓ Passed
Next expiry date	2025-03-20
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Rear exhaust damaged/corroded/deteriortaing
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6**

2024-03-07 15:57

MOT test number

681763366941

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

Advice

Rear exhaust damaged/corroded/deteriorating

Advice

Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice

Both front wiper blades starting not to clear effectively

Advice

Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #5

2022-03-09 16:08

MOT test number

743548796694

Result**✓ Passed****Advice**Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))**Advice**Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

**MOT #4**

2022-03-08 13:04

MOT test number

579299175497

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both Sides (1.1.14 (a) (ii))
- Fail** Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))

MOT #3

2021-02-15 15:53

MOT test number

799621705507

Result**✓ Passed****MOT #2**

2019-06-04 10:16

MOT test number

990127376617

Result**✓ Passed**

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Upper Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #1	2018-06-20 10:49
MOT test number	399342488297
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YY15RPU
Plate since	2015-09-29
Current registration	YY15RPU
Plate since	2015-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-26
Last registration	2024-03-21
Complete history	See info



Registration #1	2015-06-26	10 mi
Registration #2	2018-06-20	74.676 mi
Registration #3	2019-06-04	103.525 mi
Registration #4	2020-06-04	113.525 mi
Registration #5	2021-02-15	130.297 mi
Registration #6	2022-06-04	140.297 mi
Registration #7	2023-06-04	150.297 mi
Registration #8	2024-03-21	160.297 mi
Registration #9	2024-03-21	170.297 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4406 mm
Wheel base	2755 mm
Kerb weight	1430 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7267140