



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	White
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-06-29
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-14
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	20
Total items failed	9

MOT #10	2023-10-28 09:25
MOT test number	369117565557
Result	✓ Passed
Next expiry date	2024-11-11
Advice	Coil spring corroded nearside and offside front (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2023-10-26 10:07**MOT test number** 499207322176**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Coil spring corroded nearside and offside front (5.3.1 (b) (i))**Fail** Nearside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2022-10-21 09:18**MOT test number** 965585711573**Result** ✓ Passed**MOT #7** 2021-11-12 13:37**MOT test number** 502023920410**Result** ✓ Passed

**MOT #6** 2021-11-11 15:33**MOT test number** 203892257646**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #5 2021-02-04 16:14**MOT test number** 347400200200**Result** ✓ Passed

- Advice** Front slam panel deformed
- Advice** Front bumper damaged

MOT #4 2019-07-25 12:06**MOT test number** 571354383504**Result** ✓ Passed

- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))

MOT #3 2019-07-25 12:06**MOT test number** 568345933969**Result** ✗ Failed

- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))



MOT #22018-07-13 08:20

MOT test number670529555141

Result

✓ Passed

- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceOffside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- AdviceFront cross member buckled
- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- AdviceIntegral body structure is deformed but structural rigidity is not significantly reduced front slam panel (6.1.1 (a) (i))

MOT #12017-07-24 15:26

MOT test number526876123424

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
11 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	11 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	CA14KLE
Plate since	2024-03-29
Current registration	CA14KLE
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-26
Last registration	2023-10-28
Complete history	See info



Registration #1	2014-06-26	19 mi
Registration #2	2017-07-24	39.232 mi
Registration #3	2018-07-13	46.869 mi
Registration #4	2019-07-25	53.731 mi
Registration #5	2019-07-25	53.731 mi
Registration #6	2021-02-04	64.191 mi
Registration #7	2023-10-28	64.191 mi
Registration #8	2023-10-28	64.191 mi
Registration #9	2023-10-28	64.191 mi
Registration #10	2023-10-28	64.191 mi
Registration #11	2023-10-28	64.191 mi
Registration #12	2023-10-28	64.191 mi
Registration #13	2023-10-28	64.191 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1754073