



report date: 2024-03-29

General information

Make	MINI
Model	COUNTRYMAN COOPER SD COOPER SD
Colour	Grey
Year of manufacture	2012
Top speed	123 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-02-04
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-02-08
<b>MOT pass rate</b>	83 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	10
<b>Total items failed</b>	2

**MOT #12** 2024-02-09 15:39**MOT test number** 111107850864**Result** Passed**Next expiry date** 2025-02-08

- Advice** Front Items removed from driver's view prior to test
- Minor** Front Window damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2023-02-09 16:00**MOT test number** 527745074964**Result** Passed**MOT #10** 2021-12-14 09:12**MOT test number** 710546801721**Result** Passed

- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9** 2021-12-09 16:52**MOT test number** 693354253406**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #8** 2020-12-10 11:50**MOT test number** 125389047270**Result** ✓ Passed**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (ii))**MOT #7** 2020-12-10 11:02**MOT test number** 198117532096**Result** ✗ Failed**Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (ii))**MOT #6** 2019-11-29 11:05**MOT test number** 130132969053**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))**MOT #5** 2018-12-14 09:14**MOT test number** 160913345718**Result** ✓ Passed**MOT #4** 2017-12-08 09:59**MOT test number** 374229809790**Result** ✓ Passed



MOT #3	2016-12-16 09:42
MOT test number	378960942837
Result	✓ Passed
MOT #2	2015-12-22 14:50
MOT test number	123920519239
Result	✓ Passed
MOT #1	2015-06-04 12:52
MOT test number	447265855110
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
8 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	8 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>BL12ZJX</b>
Plate since	2019-09-29
Current registration	<b>BL12ZJX</b>
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-08-15
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2012-08-15	14 mi
Registration #2	2015-06-04	18.307 mi
Registration #3	2015-12-22	20.955 mi
Registration #4	2016-12-16	27.328 mi
Registration #5	2017-12-08	30.931 mi
Registration #6	2018-12-14	34.832 mi
Registration #7	2019-11-29	41.583 mi
Registration #8	2020-05-20	45.277 mi
Registration #9	2020-05-20	45.277 mi
Registration #10	2020-05-20	45.277 mi
Registration #11	2020-05-20	45.277 mi
Registration #12	2020-05-20	45.277 mi
Registration #13	2020-05-20	45.277 mi
Registration #14	2020-05-20	45.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	72978245