



RENAULT

SD62ZGE


report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LH29 DCI H/R P/V
Colour	Blue
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	39.8 mpg
Consumption combined	35.8 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-02-28
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-11
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	18
Total items failed	18

MOT #16	2023-06-12 13:59
MOT test number	216851933431
Result	✓ Passed
Next expiry date	2024-06-11

MOT #15	2023-06-08 12:42
MOT test number	281203518103
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #14**

2022-05-31 11:08

MOT test number

857825093575

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Park brake requirements only just met. It would appear that the braking system requires adjustment or repair
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13

2021-02-24 17:31

MOT test number

927870321377

Result

✓ Passed

- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #12

2021-02-23 16:28

MOT test number

717473617557

Result

✗ Failed

- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #11**

2021-02-17 16:01

MOT test number

941141113650

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Brake pipe excessively corroded above subframe (1.1.11 (c))

MOT #10

2020-02-25 11:01

MOT test number

935882363571

Result**✓ Passed**

- Advice** Central Brake pipe corroded, covered in grease or other material greased (1.1.11 (c))

MOT #9

2020-02-24 16:00

MOT test number

479646074104

Result**✗ Failed**

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Central Brake pipe corroded, covered in grease or other material greased (1.1.11 (c))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #8

2019-04-30 16:12

MOT test number

596593542307

Result**✓ Passed**

**MOT #7** 2019-04-30 15:09**MOT test number** 432950210794**Result** ✗ Failed**Fail** Nearside Rear Position lamp not working (4.2.1 (a))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2018-04-17 15:44**MOT test number** 461656614139**Result** ✓ Passed**MOT #5** 2018-04-16 14:24**MOT test number** 485257868559**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2017-04-13 06:11**MOT test number** 774566413739**Result** ✓ Passed**MOT #3** 2017-04-13 06:11**MOT test number** 406160561476**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #2** 2016-05-12 17:55**MOT test number** 267236834140**Result** ✓ Passed



MOT #1	2015-07-06 11:36
MOT test number	139807085175
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
11 June 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		11 June 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SD62ZGE
Plate since	2019-03-29
Current registration	SD62ZGE
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-10-31
Last registration	2023-06-12
Complete history	See info



Registration #1	2012-10-31	10 mi
Registration #2	2015-07-06	38.583 mi
Registration #3	2016-05-12	57.081 mi
Registration #4	2017-04-13	72.962 mi
Registration #5	2017-04-13	72.962 mi
Registration #6	2018-04-16	87.064 mi
Registration #7	2018-04-17	87.064 mi
Registration #8	2019-04-30	100.299 mi
Registration #9	2019-04-30	100.299 mi
Registration #10	2019-04-30	100.299 mi
Registration #11	2019-04-30	100.299 mi
Registration #12	2019-04-30	100.299 mi
Registration #13	2019-04-30	100.299 mi
Registration #14	2019-04-30	100.299 mi
Registration #15	2019-04-30	100.299 mi
Registration #16	2019-04-30	100.299 mi
Registration #17	2019-04-30	100.299 mi
Registration #18	2019-04-30	100.299 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C040588