



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC 16V
Colour	Silver
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	38.7 mpg
Consumption combined	30.1 mpg
CO2 emission	218 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-12
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-03
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	37
Total items failed	19

MOT #21	2023-05-04 13:39
MOT test number	628139080261
Result	✓ Passed
Next expiry date	2024-05-03
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement rear d bushes (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #20**

2023-04-26 08:58

**MOT test number**

167325257664

**Result****✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement rear d bushes (5.3.4 (a) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated perished and poorly fitted clip (6.1.7 (g) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #19**

2022-05-03 09:19

**MOT test number**

371092877631

**Result****✓ Passed****Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake hose slightly deteriorated nearside and offside (1.1.12 (b) (ii))**MOT #18**

2021-04-28 16:04

**MOT test number**

293702061684

**Result****✓ Passed**

**MOT #17** 2021-04-26 16:11**MOT test number** 960935480266**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #16** 2020-05-29 08:49**MOT test number** 754892736920**Result** ✓ Passed**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #15** 2019-05-10 14:49**MOT test number** 529408978895**Result** ✓ Passed**MOT #14** 2018-03-28 08:17**MOT test number** 952428586535**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Outer Road wheel slightly damaged rim (4.2.A.1a)

**MOT #13**

2017-03-30 11:08

**MOT test number**

406573972074

**Result**

✓ Passed

**Advice** Front Brake pads 2/3,s worn**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Tyre worn on outer edge**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #12**

2016-03-24 11:22

**MOT test number**

559883260163

**Result**

✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pads 2/3,s worn**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #11**

2015-03-13 16:25

**MOT test number**

629622475014

**Result**

✓ Passed

**Notice** Drivers side rear bumper adrift

**MOT #10**

2014-03-21 15:25

**MOT test number**

416960684095

**Result**

✓ Passed

- Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/front tyre is worn on the inner & outer edges & has slight damage on the tread just reaches the minimum requirement at time of the mot
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)

**MOT #9**

2013-03-12 14:38

**MOT test number**

266751573031

**Result**

✓ Passed

- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Dampness inside rear boot area and reversing light lenses

**MOT #8**

2012-02-23 16:21

**MOT test number**

575504352053

**Result**

✓ Passed

**MOT #7** 2012-02-23 08:29**MOT test number** 969154952093**Result** ✗ Failed

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Washer jets need cleaning and adjusting
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #6** 2011-02-22 12:41**MOT test number** 676423051073**Result** ✓ Passed

- Notice** O/s rear wheel outer rim damaged not excessive or effecting tyre wall at time of test but suggest change to avoid possible blow out
- Notice** Nail in offside rear tyre

**MOT #5** 2010-03-02 14:01**MOT test number** 964881760003**Result** ✗ Failed

- Pass with rectification** Centre Exhaust system not adequately supported (7.1.1)

**MOT #4** 2010-03-02 14:01**MOT test number** 210861260017**Result** ✓ Passed**MOT #3** 2009-03-03 12:34**MOT test number** 662262169068**Result** ✓ Passed





MOT #2	2008-03-22 10:18
MOT test number	482302788095
Result	✓ Passed

MOT #1	2008-03-21 14:51
MOT test number	293011888019
Result	✗ Failed
<div><div>Fail</div>Offside Front Tyre has ply or cords exposed (4.1.D.1b)</div>	
<div><div>Fail</div>Offside Windscreen washer provides insufficient washer liquid (8.2.3)</div>	
<div><div>Fail</div>Nearside Windscreen washer provides insufficient washer liquid (8.2.3)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
3 May 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	3 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-04-27
Last registration	2023-05-04
Complete history	<a href="#">See info</a>



Registration #1	2005-04-27	11 mi
Registration #2	2008-03-21	23.957 mi
Registration #3	2008-03-22	23.957 mi
Registration #4	2009-03-03	28.358 mi
Registration #5	2010-03-02	31.771 mi
Registration #6	2011-02-22	35.197 mi
Registration #7	2012-02-23	39.129 mi
Registration #8	2012-02-23	39.129 mi
Registration #9	2013-03-12	41.678 mi
Registration #10	2014-03-21	45.029 mi
Registration #11	2015-03-13	49.582 mi
Registration #12	2016-03-20	54.135 mi
Registration #13	2017-03-20	58.688 mi
Registration #14	2018-03-20	63.241 mi
Registration #15	2019-03-20	67.794 mi
Registration #16	2020-03-20	72.347 mi
Registration #17	2021-03-20	76.900 mi
Registration #18	2022-03-20	81.453 mi
Registration #19	2023-03-20	86.006 mi
Registration #20	2024-03-20	90.559 mi
Registration #21	2025-03-20	95.112 mi
Registration #22	2026-03-20	99.665 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1931 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1415 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	5G46133