



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI (110BHP) DESIRE PICASSO
Colour	Purple
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-18
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #24	2021-02-19 12:46
MOT test number	591739431895
Result	✓ Passed
Next expiry date	2022-02-18
Advice	SLIGHT PLAY IN ENGINE MOUNT
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #23	2019-10-17 15:12
MOT test number	430445066220
Result	✓ Passed
Advice	Under shields fitted

MOT #22	2019-09-25 10:14
MOT test number	555072775997
Result	✗ Failed
Advice	N/s/f sill corroded in hole
DANGEROUS	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
Advice	Under shields fitted
MAJOR	Engine mounting damaged or deteriorated resulting in excessive movement lower mounting (6.1.8 (a) (i))
DANGEROUS	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #21	2018-10-08 14:26
MOT test number	612863903635
Result	✓ Passed
Advice	Corrosion n/s/f and o/s/f outer sills

**MOT #20** 2018-10-08 08:50**MOT test number** 769358154411**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Corrosion n/s/f and o/s/f outer sills**MAJOR** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**MOT #19** 2017-10-10 14:51**MOT test number** 270480045859**Result** ✓ Passed**MOT #18** 2016-10-10 14:53**MOT test number** 929203645532**Result** ✓ Passed**Advice** O/S Outer sill slightly corroded**MOT #17** 2015-10-09 12:37**MOT test number** 351848022380**Result** ✓ Passed**Advice** O/S Outer sill deteriorated**Advice** O/S/R Tyre cracking

**MOT #16** 2015-10-08 11:30**MOT test number** 584829635017**Result** ✗ Failed**Advice** O/S Outer sill deteriorated**Fail** Nearside rear brake binding (3.7.B.1)**Advice** O/S/R Tyre cracking**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #15** 2014-10-15 09:09**MOT test number** 957768884240**Result** ✓ Passed**MOT #14** 2014-10-14 10:40**MOT test number** 227657884212**Result** ✗ Failed**Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)**MOT #13** 2013-10-07 15:08**MOT test number** 936820483296**Result** ✓ Passed



MOT #12 2013-10-07 10:51

MOT test number 895610383221

Result ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #11 2012-10-10 15:45

MOT test number 346104882251

Result ✓ Passed

- Advice** Offside Front Side repeater slightly discoloured (1.4.A.2f)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Damage too tyres sidewall on all tyres exhaust heat sheild loose //
- Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #10** 2012-10-10 10:23**MOT test number** 289194482216**Result** ✗ Failed**Advice** Nearside Rear Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Front Steering system has a tyre fouling a part of the vehicle (2.2.D.2a)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Side repeater slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Notice** Damage too tyres sidewall on all tyres exhaust heat shield loose //**Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)**MOT #9** 2011-10-04 10:24**MOT test number** 289667271275**Result** ✓ Passed**MOT #8** 2011-10-04 10:24**MOT test number** 488927571252**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #7** 2010-10-11 11:29**MOT test number** 104594480232**Result** ✓ Passed

**MOT #6** 2010-10-11 10:32**MOT test number** 702174780200**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)**MOT #5** 2009-09-24 14:28**MOT test number** 462837369202**Result** ✓ Passed**MOT #4** 2009-09-22 10:19**MOT test number** 152895069216**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Offside Front Headlamp aim too low (1.8)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #3** 2008-10-02 09:39**MOT test number** 452186178260**Result** ✓ Passed



MOT #2	2008-09-30 15:30
MOT test number	121264178297
Result	✗ Failed
Fail	Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)
Fail	Offside Rear Direction indicators not working (1.4.A.2c)
Fail	Offside Headlamp aim too low (1.8)
Fail	Stop lamp not working (1.2.1b)
Fail	Offside Rear Hazard warning lamps not flashing in phase, with ignition on (1.4.B.1f)

MOT #1	2007-10-17 13:34
MOT test number	924490497217
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-11-19
Last registration	2021-02-19
Complete history	See info



Registration #1	2004-11-19	6 mi
Registration #2	2007-10-17	60.353 mi
Registration #3	2008-09-30	67.891 mi
Registration #4	2008-10-02	67.891 mi
Registration #5	2009-09-22	7.816 mi
Registration #6	2009-09-24	7.816 mi
Registration #7	2010-10-11	73.649 mi
Registration #8	2010-10-11	73.649 mi
Registration #9	2011-10-04	76.098 mi
Registration #10	2012-10-10	78.477 mi
Registration #11	2012-10-10	78.477 mi
Registration #12	2013-10-07	80.669 mi
Registration #13	2013-10-07	80.669 mi
Registration #14	2013-10-07	80.669 mi
Registration #15	2013-10-07	80.669 mi
Registration #16	2013-10-07	80.669 mi
Registration #17	2013-10-07	80.669 mi
Registration #18	2013-10-07	80.669 mi
Registration #19	2013-10-07	80.669 mi
Registration #20	2013-10-07	80.669 mi
Registration #21	2013-10-07	80.669 mi
Registration #22	2013-10-07	80.669 mi
Registration #23	2013-10-07	80.669 mi
Registration #24	2013-10-07	80.669 mi
Registration #25	2013-10-07	80.669 mi



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1705 mm
Height	1420 mm
Length	4369 mm
Wheel base	2760 mm
Kerb weight	1313 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB010041852