





report date: 2024-03-28

# General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Red
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

Entry	1

Lifety 1	
Date	2022-05-18
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



GM15GYK report date: 2024-03-28

MOT history

MOT expiry date	2024-06-23
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #7	2023-06-23 14:04
MOT test number	194816010220
Result	✓ Passed
Next expiry date	2024-06-23
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #6	2022-06-09 15:33
MOT test number	978275474119
Result	✓ Passed
Advice Central Rear Exhaust mounting defective (6.1.2 (a))	

MOT #5	2021-06-22 08:03
MOT test number	349181971359
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

651082446541

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-06-11 07:50

MOT test number 514138845524

Result ✓ Passed

MOT #2 2019-06-08 07:55

MOT test number 647600819364

Result ✓ Passed

MOT #1 2018-06-15 09:02

MOT test number 624333828465

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre wearing along inner egde

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	23 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Ow		la : -	
( )\//	ner	nis	

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

## Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-24
Last registration	2023-06-23
Complete history	See info



Registration #1	2015-06-24	19 mi
Registration #2	2018-06-15	14.918 mi
Registration #3	2019-06-08	22.292 mi
Registration #4	2020-06-11	28.934 mi
Registration #5	2021-06-22	35.154 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



GM15GYK report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

# Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961

CarCheck.co.uk page 11/11