



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Blue
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-19
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	28
Total items failed	8

MOT #15	2023-07-12 16:20
MOT test number	423037892387
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #14	2023-07-12 08:58
MOT test number	215288496566
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Headlamp aim too low (4.1.2 (a))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2022-07-12 11:33**MOT test number** 442766658240**Result** ✓ Passed**MOT #12** 2022-07-12 11:33**MOT test number** 773680461699**Result** ✗ Failed**Pass with rectification** Offside Front Direction indicator not working (4.4.1 (a) (ii))**MOT #11** 2021-07-09 10:17**MOT test number** 670363277661**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**Advice** Engine/under tray fitted**MOT #10** 2020-07-13 15:22**MOT test number** 526108253943**Result** ✓ Passed**Advice** Central Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #9** 2020-07-13 15:22**MOT test number** 392175775219**Result** ✗ Failed**Advice** Central Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))

**MOT #8** 2019-07-19 09:16**MOT test number** 277207144741**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2018-07-24 13:53**MOT test number** 656864326370**Result** ✓ Passed**MOT #6** 2017-08-05 08:43**MOT test number** 999299902024**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Eml on handbrake travel**Advice** Play in steering rack inner joint(s)**MOT #5** 2016-07-26 09:14**MOT test number** 110124337257**Result** ✓ Passed**Advice** Inner joints childseat fitted engine cover utray handbrake travel**MOT #4** 2015-08-17 09:36**MOT test number** 407499425260**Result** ✓ Passed**Notice** Handbrake travel**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2014-04-08 11:34**MOT test number** 188958394405**Result** ✓ Passed**MOT #2** 2013-04-23 09:55**MOT test number** 206553413489**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-04-22 09:49**MOT test number** 369962313105**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Headlamp aim too high (1.8)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EY10XYE
Plate since	2019-03-28
Current registration	EY10XYE
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-22
Last registration	2023-07-12
Complete history	See info



Registration #1	2010-04-22	11 mi
Registration #2	2013-04-22	25.231 mi
Registration #3	2013-04-23	25.231 mi
Registration #4	2014-04-08	36.155 mi
Registration #5	2015-08-17	53.628 mi
Registration #6	2016-07-26	62.742 mi
Registration #7	2017-08-05	71.203 mi
Registration #8	2018-07-24	80.832 mi
Registration #9	2019-07-19	935.655 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2020-05-20	95.277 mi
Registration #12	2020-05-20	95.277 mi
Registration #13	2020-05-20	95.277 mi
Registration #14	2020-05-20	95.277 mi
Registration #15	2020-05-20	95.277 mi
Registration #16	2020-05-20	95.277 mi
Registration #17	2020-05-20	95.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

AB89987