



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC DYNAMIQUE DCI 106 G/SCENIC
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	240 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	57.6 mpg
Consumption combined	52.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-26
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT #14 2018-10-23 09:55

MOT test number 369225798920

Result ✓ Passed

Next expiry date 2019-11-01

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Lower Windscreen damaged but not adversely affecting driver's view borderline (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Non obligatory mirror damaged
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2018-10-22 08:13

MOT test number

357360827283

Result**✗ Failed****MAJOR** Bonnet primary retaining device ineffective (3.1 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Play in steering rack inner joint(s)**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Nearside Lower Windscreen damaged but not adversely affecting driver's view borderline (3.2 (a) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Non obligatory mirror damaged**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Play in steering rack inner joint(s)**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12**

2017-10-31 12:10

MOT test number

490166330301

Result

✓ Passed

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Non obligatory mirror damaged
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Play in steering rack inner joint(s)

MOT #11

2017-10-31 11:16

MOT test number

901969917344

Result

✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Non obligatory mirror damaged

MOT #10

2016-11-02 16:53

MOT test number

943121328962

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Play in steering rack inner joint(s) nearside and offside
- Advice** Crack to nearside of windscreen but not seriously affecting the driver view of the road

**MOT #9** 2015-10-12 12:56**MOT test number** 560443409515**Result** ✓ Passed**Advice** Both rear tyres wearing low**Advice** Front brake pads wearing low**Advice** Rear brake pads wearing low**MOT #8** 2015-10-12 10:01**MOT test number** 486709380856**Result** ✗ Failed**Advice** Rear brake pads wearing low**Advice** Both rear tyres wearing low**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front brake pads wearing low**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #7** 2014-10-10 13:01**MOT test number** 426633984283**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #6** 2014-10-10 09:53**MOT test number** 806713584204**Result** ✗ Failed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-10-28 16:00**MOT test number** 679591803318**Result** ✓ Passed**MOT #4** 2012-10-02 17:03**MOT test number** 396706072455**Result** ✓ Passed**MOT #3** 2012-10-02 10:32**MOT test number** 626006272214**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Front brake discs are worn**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brake discs are worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-10-03 11:46**MOT test number** 316726871494**Result** ✓ Passed



MOT #1	2010-10-11 12:34
MOT test number	624534480293
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Rear pads are worn
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-10-26
Last registration	2018-10-23
Complete history	See info



Registration #1	2007-10-26	27 mi
Registration #2	2010-10-11	25.949 mi
Registration #3	2011-10-03	36.198 mi
Registration #4	2012-10-02	45.110 mi
Registration #5	2012-10-02	45.110 mi
Registration #6	2013-10-28	54.878 mi
Registration #7	2014-10-10	64.284 mi
Registration #8	2014-10-10	64.284 mi
Registration #9	2015-10-02	73.277 mi
Registration #10	2015-10-02	73.277 mi
Registration #11	2015-10-02	73.277 mi
Registration #12	2015-10-02	73.277 mi
Registration #13	2015-10-02	73.277 mi
Registration #14	2015-10-02	73.277 mi
Registration #15	2015-10-02	73.277 mi
Registration #16	2018-10-23	73.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1490 kg
Max. allowed weight	2165 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D361131
---------------	---------