



report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Blue
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-09-06
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-04
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	33
Total items failed	30

MOT #19 2023-10-05 12:52

MOT test number 735273537747

Result ✓ Passed

Next expiry date 2024-10-04

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18 2022-09-16 09:10

MOT test number 490084967571

Result ✓ Passed

MOT #17 2022-09-12 13:00

MOT test number 123934995137

Result ✗ Failed

Fail Nearside Front Lower Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Rear Lower Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #16** 2021-09-16 11:51**MOT test number** 941336354967**Result** ✓ Passed**MOT #15** 2021-09-13 09:26**MOT test number** 473229415865**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #14** 2020-12-12 10:56**MOT test number** 101698153554**Result** ✓ Passed**Advice** Rear blade split**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2020-12-11 14:32

MOT test number

112231942269

Result

✗ Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear blade split**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Electronic parking brake warning indicates a malfunction (1.1.6 (e))**Fail** Offside Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Headlamp aim too low and too far to the left. (4.1.2 (a))**Fail** Electronic parking brake control inoperative (1.1.6 (d))**Advice** Rear exhaust heat shield insecure**Fail** Nearside Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))**MOT #12**

2019-12-17 16:00

MOT test number

605517033354

Result

✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt**Advice** REAR WIPER SPLIT

**MOT #11** 2019-12-17 10:51**MOT test number** 522754946705**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** REAR WIPER SPLIT**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2018-12-14 14:36**MOT test number** 570661134247**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-12-14 10:08**MOT test number** 337511403616**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #8** 2017-12-22 10:51**MOT test number** 286366881101**Result** ✓ Passed**Advice** Offside Rear tyre on 2.00mm and cracking on outer sidewall**Advice** Child Seat fitted not allowing full inspection of adult belt in rear**MOT #7** 2017-12-22 10:51**MOT test number** 961826187772**Result** ✗ Failed**Advice** Offside Rear tyre on 2.00mm and cracking on outer sidewall**Pass with rectification** Offside Front Windscreen wiper blade insecure (8.2.2)**Advice** Child Seat fitted not allowing full inspection of adult belt in rear**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2016-12-23 09:49**MOT test number** 253801677647**Result** ✓ Passed**MOT #5** 2016-12-23 09:49**MOT test number** 923416466597**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #4** 2015-12-29 09:17**MOT test number** 311821150486**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**MOT #3** 2015-12-29 09:17**MOT test number** 390306258705**Result** ✗ Failed**Pass with rectification** Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2014-12-10 15:05**MOT test number** 667944344375**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2013-12-14 10:49**MOT test number** 497768043455**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-12-29
Last registration	2023-10-05
Complete history	See info



Registration #1	2010-12-29	11 mi
Registration #2	2013-12-14	26.195 mi
Registration #3	2014-12-10	35.270 mi
Registration #4	2015-12-29	49.351 mi
Registration #5	2015-12-29	49.351 mi
Registration #6	2016-12-23	62.407 mi
Registration #7	2016-12-23	62.407 mi
Registration #8	2017-12-22	73.513 mi
Registration #9	2017-12-22	73.513 mi
Registration #10	2018-12-14	84.049 mi
Registration #11	2018-12-14	84.050 mi
Registration #12	2019-05-29	85.277 mi
Registration #13	2019-05-29	85.277 mi
Registration #14	2019-05-29	85.277 mi
Registration #15	2019-05-29	85.277 mi
Registration #16	2019-05-29	85.277 mi
Registration #17	2019-05-29	85.277 mi
Registration #18	2019-05-29	85.277 mi
Registration #19	2019-05-29	85.277 mi
Registration #20	2019-05-29	85.277 mi
Registration #21	2019-05-29	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0086665