





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND PICASSO GRAND BLUEHDI SELECTION
Colour	Red
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date	2023-03-22
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2

Date	2023-02-16	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

Entry 1

Date	2021-01-29
Pictures	9
Listing price	<u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT I	nistory
-------	---------

MOT expiry date	2025-04-08
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #8	2024-04-09 10:49
MOT test number	706562220897
Result	✓ Passed
Next expiry date	2025-04-08

MOT #7	2024-04-09 10:49
MOT test number	936075265018
Result	▼ Failed
Pass with rectification	Offside Front Prop shaft joint constant velocity boot missing (6.1.7 (g) (ii))
Pass with rectification ingress of dirt (6.1.7 (g) (ii))	Nearside Front Prop shaft joint constant velocity boot no longer prevents the

MOT #6	2023-05-19 09:46
MOT test number	331368209937
Result	✓ Passed

MOT #5		2023-05-17 10:37
MOT test number	er	457933750472
Result		X Failed
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm 20	5/55 17 (5.2.3 (e))
Advice Nears	side Front Tyre worn close to legal limit/worn on edge 2.6mm (5.2	.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2021-09-29 10:39 478622320134 **MOT** test number Result ✓ Passed Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Advice Third row seats stowed away not allowing full inspection of belts and seats Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice **Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2	2020-10-02 13:54
MOT test number	393328533175
Result	✓ Passed
MOT #1	2019-09-11 10:43
MOT test number	672390843095
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim		histor	
- () ()	vnor	nictoi	↷

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		OEN
manage of the same		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK NEZ	
Plate since		
Current registration	UK NIE	
Plate since		
	More info	
	More into	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-09-30
Last registration	2024-04-09
Complete history	See info



Registration #1	2016-09-30	22 mi
Registration #2	2019-09-11	12.713 mi
Registration #3	2020-10-02	19.290 mi
Registration #4		D.777 es
Registration #5	2021-09-29	27.690 mi
Registration #6	2022-10-17	44.012 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1347 kg
Max. allowed weight	2175 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBGY3086510

CarCheck.co.uk page 11/11