





report date: 2024-03-29

General information

Make	BMW
Model	730 730D SE
Colour	Grey
Year of manufacture	2009
Top speed	153 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	241 BHP
Max. torque	540 Nm at 1.750 rpm
Engine capacity	3.000 cc
Cylinders	6
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	192 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-19

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim	- 1				
Μ	()	1	าเ	ST	'n	rv

MOT expiry date	2024-10-30
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #16		2023-10-31 11:10
MOT test	number	368106397753
Result		✓ Passed
Next expi	ry date	2024-10-30
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4
Advice	Rear Inner Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	

MOT #15		2022-10-31 15:52
MOT test	number	715266701180
Result		✓ Passed
Advice	Offside Front Nail in tyre	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



Advice

UNDERTRAYS FITTED

MF59HZM

report date: 2024-03-29

MOT #14 2022-10-25 14:01 **MOT** test number 675986464157 Result × Failed **Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail **Advice** Offside Front Nail in tyre

 MOT #13
 2021-10-25 18:34

 MOT test number
 228569284271

 Result
 ✓ Passed

 MOT #12
 2020-10-26 16:29

 MOT test number
 922444215218

 Result
 ✓ Passed

MOT test number

Result

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

CarCheck.co.uk page 4/13




MOT #9

MF59HZM

report date: 2024-03-29

2018-10-22 09:31



MOT test number	827088785702
Result	✓ Passed
MOT #8	2018-10-20 10:31
MOT test number	167691630706
Result	★ Failed
Fail Nearside Rear Tyre has ply	or cords exposed (5.2.3 (d) (ii))
Fail Offside Rear Tyre has ply or	cords exposed (5.2.3 (d) (ii))

MOT #7	2017-10-21 14:42
MOT test number	158030544240
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 5/13



(2.4.G.2)

MF59HZM

report date: 2024-03-29

MOT #6 2017-10-21 09:51

MOT test number 770954618203

Result X Failed

Fail Nearside Headlamp cleaning device inoperative (1.7.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2016-10-26 14:54

MOT test number 157119397065

Result
✓ Passed

MOT #4 2015-10-06 13:46

MOT test number 770955446854

Result \rightarrow Passed

MOT #3 2014-09-08 12:08

MOT test number 895551854208

Result
✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

MOT #2 2013-08-09 12:51

MOT test number 269761623246

MOT #1 2012-08-10 13:46

MOT test number 839563022231

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO. C.	

THE STATE OF THE S	
HARMAN AND AND AND AND AND AND AND AND AND A	

THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-01
Last registration	2023-10-31
Complete history	See info



Registration #1	2009-09-01	6 mi
Registration #2	2012-08-10	35.954 mi
Registration #3	2013-08-09	48.222 mi
Registration #4	2014-09-08	57.907 mi
Registration #5	2015-10-06	67.675 mi
Registration #6	2016-10-26	81.556 mi
Registration #7	2017-10-21	95.358 mi
Registration #8	2017-10-21	95.358 mi
Registration #9	2018-10-20	102.785 mi
Registration #10		77,777 44
Registration #11		11.777 es
Registration #12		77,777 44
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1902 mm
Height	1488 mm
Length	5072 mm
Wheel base	3070 mm
Kerb weight	1940 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 24367196