



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 MWB DRW C/C
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT expiry date	2021-11-05
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	30
Total items failed	7

MOT #16	2020-11-06 10:28
MOT test number	723718757362
Result	✓ Passed
Next expiry date	2021-11-05

MOT #15	2019-04-25 12:43
MOT test number	892931991511
Result	✓ Passed

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside inner wheel rim and brake drum appears wet with brake fluid
- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear mount (5.3.4 (a) (i))
- Advice** Offside rear inner and outer sills corroded
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))

**MOT #14**

2019-04-23 11:47

MOT test number

625026813289

Result

✗ Failed

Fail

Brake fluid significantly below minimum mark (1.1.10 (d) (ii))

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear mount (5.3.4 (a) (i))

Minor

Brake fluid warning lamp illuminated (1.1.10 (f))

Advice

Offside inner wheel rim and brake drum appears wet with brake fluid

Minor

Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Fail

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail

Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice

Offside rear inner and outer sills corroded

Advice

Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Power steering close to minimum mark (2.1.5 (b) (i))

Fail

Horn not working (7.7 (a) (ii))

MOT #13

2018-04-30 15:47

MOT test number

857974915140

Result

✓ Passed

MOT #12

2017-04-26 08:34

MOT test number

690265717465

Result

✓ Passed

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #11** 2016-08-04 14:26**MOT test number** 112050620591**Result** ✓ Passed**Advice** Drivers seat slightly damaged**MOT #10** 2016-08-04 14:26**MOT test number** 318990871046**Result** ✗ Failed**Advice** Drivers seat slightly damaged**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #9** 2015-08-03 09:01**MOT test number** 245785215292**Result** ✓ Passed**MOT #8** 2015-07-30 17:16**MOT test number** 668281615285**Result** ✗ Failed**Fail** Offside Rear position lamp(s) incorrect colour (1.1.A.3e)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #7** 2014-08-01 12:24**MOT test number** 916813014292**Result** ✓ Passed**Advice** Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

**MOT #6** 2013-07-24 16:52**MOT test number** 869815803271**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)
- Advice** Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2012-07-12 14:26**MOT test number** 437214092114**Result** ✓ Passed**MOT #4** 2011-07-13 15:58**MOT test number** 278774191442**Result** ✓ Passed**MOT #3** 2010-07-06 15:57**MOT test number** 134487780154**Result** ✓ Passed

- Notice** Hazard switch worn
- Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both rear roll bar drop links worn
- Notice** Nearside rear marker light
- Advice** Offside Outer Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-06-19 13:02
MOT test number	490940779151
Result	✓ Passed

MOT #1	2008-08-02 09:14
MOT test number	674835118238
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
4 January 2021

✕
MOT

Expired:
5 November 2021

Tax status	Expired at 4 January 2021
Days left	1212 days too late
MOT expiry date	5 November 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2005-06-02
Last registration	2020-11-06
Complete history	See info



Registration #1	2005-06-02	24 mi
Registration #2	2008-08-02	54.983 mi
Registration #3	2009-06-19	71.216 mi
Registration #4	2010-07-06	89.083 mi
Registration #5	2011-07-13	110.394 mi
Registration #6	2012-07-12	127.009 mi
Registration #7	2013-07-24	140.487 mi
Registration #8	2014-08-01	153.681 mi
Registration #9	2015-05-20	165.277 mi
Registration #10	2016-05-20	175.277 mi
Registration #11	2017-05-20	185.277 mi
Registration #12	2018-05-20	195.277 mi
Registration #13	2019-05-20	205.277 mi
Registration #14	2020-05-20	215.277 mi
Registration #15	2020-11-06	224.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	5C67224