



report date: 2024-03-28

## General information

Make	NISSAN
Model	NOTE ACENTA
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	87 BHP
Max. torque	128 Nm at 3.200 rpm
Engine capacity	1.386 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.7 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	9
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)



## MOT history

MOT expiry date	2025-02-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	20
Total items failed	9

MOT #14	2024-01-15 09:54
MOT test number	551092710718
Result	✓ Passed
Next expiry date	2025-02-04

MOT #13	2024-01-11 13:39
MOT test number	502828043721
Result	✗ Failed
<b>Pass with rectification</b> Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Fail</b> Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #12	2023-01-23 15:43
MOT test number	743946631807
Result	✓ Passed
<b>Advice</b> Brake pad(s) wearing thin nearside and offside front (1.1.13 (a) (ii))	
<b>Advice</b> Brake disc worn, pitted or scored, but not seriously weakened nearside and offside front (1.1.14 (a) (ii))	

**MOT #11** 2023-01-23 09:36**MOT test number** 375396283417**Result** ✗ Failed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened nearside and offside front (1.1.14 (a) (ii))

**Advice** Brake pad(s) wearing thin nearside and offside front (1.1.13 (a) (ii))

**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #10** 2022-01-12 14:22**MOT test number** 808426715607**Result** ✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2021-02-05 07:46**MOT test number** 290777394596**Result** ✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2020-09-01 11:37**MOT test number** 516684564160**Result** ✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-08-20 14:45**MOT test number** 546656602033**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-09-05 19:26**MOT test number** 820237613981**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2017-08-11 10:35**MOT test number** 139343385704**Result** ✓ Passed**MOT #4** 2017-08-10 09:54**MOT test number** 256133211608**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear arm bush (2.4.G.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #3** 2016-08-22 08:18**MOT test number** 808912960599**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2015-09-09 23:48**MOT test number** 558667422597**Result** ✓ Passed**MOT #1** 2015-06-10 09:36**MOT test number** 109241465114**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
4 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	4 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-08-30
Last registration	2024-01-15
Complete history	<a href="#">See info</a>



Registration #1	2012-08-30	9 mi
Registration #2	2015-06-10	10.808 mi
Registration #3	2015-09-09	11.830 mi
Registration #4	2016-08-22	22.693 mi
Registration #5	2017-08-10	36.243 mi
Registration #6	2017-08-11	36.243 mi
Registration #7	2018-09-05	44.786 mi
Registration #8	2019-08-20	51.121 mi
Registration #9	2020-09-01	59.873 mi
Registration #10	2020-09-01	59.873 mi
Registration #11	2020-09-01	59.873 mi
Registration #12	2020-09-01	59.873 mi
Registration #13	2020-09-01	59.873 mi
Registration #14	2020-09-01	59.873 mi
Registration #15	2020-09-01	59.873 mi
Registration #16	2020-09-01	59.873 mi
Registration #17	2020-09-01	59.873 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1691 mm
Height	1550 mm
Length	4083 mm
Wheel base	2600 mm
Kerb weight	1092 kg
Max. allowed weight	1546 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	326060
---------------	--------