



AD06AFV

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	JETTA S TDI
Colour	Blue
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg





Internet history

Entry 1

Date	2021-10-19
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #17	2021-06-22 09:36
MOT test number	641721208418
Result	✓ Passed
Next expiry date	2022-06-24
Advice	Both head light lenses dull

MOT #16	2020-06-25 09:58
MOT test number	624726919099
Result	✓ Passed
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Front Seat belt buckle damaged
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2019-06-22 10:26
MOT test number	448683037049
Result	✓ Passed

MOT #14	2018-06-20 13:43
MOT test number	121245076080
Result	✓ Passed

MOT #13	2018-06-20 10:34
MOT test number	161336877194
Result	✗ Failed
Fail	Nearside Front Outer Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12** 2017-06-23 09:35**MOT test number** 781620556523**Result** ✓ Passed**MOT #11** 2017-06-23 09:35**MOT test number** 460063106431**Result** ✗ Failed

**Pass with rectification** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #10** 2016-06-09 13:34**MOT test number** 426159763209**Result** ✓ Passed**MOT #9** 2016-06-09 07:54**MOT test number** 805435737219**Result** ✗ Failed

**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Side repeater not working (1.4.A.2c)

**MOT #8** 2015-06-12 08:45**MOT test number** 138263365171**Result** ✓ Passed**MOT #7** 2014-06-16 09:14**MOT test number** 928627364144**Result** ✓ Passed

**MOT #6** 2013-06-24 09:17**MOT test number** 799095473135**Result** ✓ Passed**Notice** Front tyre worn low on inner edges.**MOT #5** 2013-06-24 09:17**MOT test number** 927255273134**Result** ✗ Failed**Notice** Front tyre worn low on inner edges.**Pass with rectification** Offside Side repeater not working (1.4.A.2c)**MOT #4** 2012-06-21 09:15**MOT test number** 716693172194**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-06-06 09:24**MOT test number** 218147451186**Result** ✓ Passed**MOT #2** 2010-06-25 09:42**MOT test number** 862956970169**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2009-06-19 09:34
MOT test number	890610479158
Result	✓ Passed
<div>Notice Child seat fitted not allowing full inspection of adult belt</div>	



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AD06AFV</b>
Plate since	2024-03-29
Current registration	 <b>AD06AFV</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-26
Last registration	2021-06-22
Complete history	<a href="#">See info</a>



Registration #1	2006-06-26	11 mi
Registration #2	2009-06-19	23.779 mi
Registration #3	2010-06-25	30.210 mi
Registration #4	2011-06-06	35.892 mi
Registration #5	2012-06-21	40.871 mi
Registration #6	2013-06-24	45.810 mi
Registration #7	2014-06-16	50.614 mi
Registration #8	2015-06-12	55.337 mi
Registration #9	2016-06-09	60.107 mi
Registration #10	2017-06-20	65.277 mi
Registration #11	2018-06-20	70.277 mi
Registration #12	2019-06-20	75.277 mi
Registration #13	2020-06-20	80.277 mi
Registration #14	2021-06-20	85.277 mi
Registration #15	2022-06-20	90.277 mi
Registration #16	2023-06-20	95.277 mi
Registration #17	2024-06-20	100.277 mi
Registration #18	2025-06-20	105.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1508 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BKC A33785