



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2014
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-05
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-08-09
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	22
Total items failed	1

MOT #9	2023-08-09 08:01
MOT test number	312010635850
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2023-08-09 08:01
MOT test number	568885736185
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2022-08-10 07:36**MOT test number** 486002686909**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2021-08-03 08:47**MOT test number** 372279938170**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #5** 2020-07-29 10:42**MOT test number** 833098161854**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-08-06 09:44**MOT test number** 398472976166**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #3	2018-08-09 11:05
MOT test number	439840468361
Result	✓ Passed

MOT #2	2018-08-09 08:12
MOT test number	526903787308
Result	✗ Failed
<b>MAJOR</b> Windscreen washer provides insufficient washer liquid (3.5 (a))	
<b>MAJOR</b> Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	

MOT #1	2017-07-29 10:06
MOT test number	109631895550
Result	✓ Passed
<b>Advice</b> Offside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Advice</b> Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
9 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	9 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KE14ZLU
Plate since	2019-06-29
Current registration	 KE14ZLU
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-31
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2014-07-31	23 mi
Registration #2	2017-07-29	53.714 mi
Registration #3	2018-08-09	68.934 mi
Registration #4	2018-08-09	68.934 mi
Registration #5	2019-08-06	77.611 mi
Registration #6	2020-07-29	87.441 mi
Registration #7	2021-08-06	95.277 mi
Registration #8	2021-08-06	95.277 mi
Registration #9	2021-08-06	95.277 mi
Registration #10	2021-08-06	95.277 mi
Registration #11	2023-08-09	95.277 mi

More info >



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005566978 LN9