



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-06
Pictures	27
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2022-11-16 12:39
MOT test number	361323761125
Result	✓ Passed
Next expiry date	2023-11-15

MOT #17	2021-11-12 20:44
MOT test number	784254230531
Result	✓ Passed

MOT #16	2021-01-12 14:35
MOT test number	254133886523
Result	✓ Passed

MOT #15	2020-02-11 11:30
MOT test number	326419389564
Result	✓ Passed

MOT #14	2019-04-16 08:39
MOT test number	372102006139
Result	✓ Passed

Advice Rear brake pads appear around 70% worn.

MOT #13	2018-03-29 12:05
MOT test number	478066184291
Result	✓ Passed

MOT #12	2018-03-29 12:05
MOT test number	797264235739
Result	✗ Failed

Pass with rectification Nearside Rear Braking system leaking Brake pipe (3.6.A.1)

Pass with rectification Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**MOT #11** 2017-04-11 08:35**MOT test number** 620054769285**Result** ✓ Passed**Advice** Replace front brake pads on or before 31/07/2017.**MOT #10** 2016-04-01 08:32**MOT test number** 885851727838**Result** ✓ Passed**MOT #9** 2015-04-09 12:02**MOT test number** 466769995087**Result** ✓ Passed**MOT #8** 2015-04-09 09:46**MOT test number** 106259095003**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**MOT #7** 2014-04-28 16:51**MOT test number** 637978514154**Result** ✓ Passed**Notice** Exhaust system(flexi - middle - rear) all have minor corrosion

**MOT #6** 2014-04-26 15:51**MOT test number** 256396114168**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Exhaust system(flexi - middle - rear) all have minor corrosion**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**MOT #5** 2013-03-27 10:18**MOT test number** 656646383001**Result** ✓ Passed**MOT #4** 2012-03-23 09:08**MOT test number** 198983382410**Result** ✓ Passed**Notice** The Rubber of all 4 tyres is deteriorating.**Notice** Inspection Lamp is Illuminating.**MOT #3** 2011-04-05 15:45**MOT test number** 176725691020**Result** ✓ Passed**MOT #2** 2010-10-11 11:41**MOT test number** 403454780205**Result** ✓ Passed



MOT #1	2010-10-11 10:36
MOT test number	352314780261
Result	✗ Failed
Fail	Offside Front Seat belt retracting mechanism defective (5.2.5b)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YR57WNC
Plate since	2019-06-29
Current registration	YR57WNC
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-15
Last registration	2022-11-16
Complete history	See info



Registration #1	2007-10-15	10 mi
Registration #2	2010-10-11	12.616 mi
Registration #3	2010-10-11	12.616 mi
Registration #4	2011-04-05	13.822 mi
Registration #5	2012-03-23	18.298 mi
Registration #6	2013-03-27	23.319 mi
Registration #7	2014-04-26	27.585 mi
Registration #8	2014-04-28	27.602 mi
Registration #9	2015-04-09	31.225 mi
Registration #10	2015-04-09	31.225 mi
Registration #11	2015-04-09	31.225 mi
Registration #12	2015-04-09	31.225 mi
Registration #13	2015-04-09	31.225 mi
Registration #14	2015-04-09	31.225 mi
Registration #15	2015-04-09	31.225 mi
Registration #16	2015-04-09	31.225 mi
Registration #17	2015-04-09	31.225 mi
Registration #18	2015-04-09	31.225 mi
Registration #19	2015-04-09	31.225 mi
Registration #20	2015-04-09	31.225 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118