



report date: 2024-03-28

General information

Make	MINI
Model	COOPER D
Colour	White
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A








Internet history

Entry 1

Date	2022-07-10
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-10
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #12	2023-06-17 08:51
MOT test number	808703094946
Result	✓ Passed
Next expiry date	2024-07-10

MOT #11	2022-07-11 11:08
MOT test number	456005553959
Result	✓ Passed

MOT #10	2022-01-12 15:15
MOT test number	773060881938
Result	✓ Passed

- Minor** Nearside Windscreen damaged but not adversely affecting driver's view Chipped (3.2 (a) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Inner surface (1.1.14 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9**

2021-01-11 12:12

MOT test number

195485893682

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8

2020-01-09 15:09

MOT test number

143200646398

Result

✓ Passed

MOT #7

2019-01-15 10:27

MOT test number

308306182744

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2018-01-15 16:22**MOT test number** 832932942811**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2018-01-15 16:22**MOT test number** 434887551825**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #4** 2017-01-11 16:37**MOT test number** 333440756890**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2016-01-18 16:54**MOT test number** 133929486355**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2016-01-18 16:54**MOT test number** 389688194725**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working blb239 bulb fitted (1.1.C.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2015-01-14 11:32
MOT test number	198684015039
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YB61LPO
Plate since	2019-09-28
Current registration	YB61LPO
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-01-16
Last registration	2023-06-17
Complete history	See info



Registration #1	2012-01-16	24 mi
Registration #2	2015-01-14	44.275 mi
Registration #3	2016-01-18	55.106 mi
Registration #4	2016-01-18	55.106 mi
Registration #5	2017-01-11	60.769 mi
Registration #6	2018-01-15	66.683 mi
Registration #7	2018-01-15	66.683 mi
Registration #8	2019-01-15	72.597 mi
Registration #9	2019-01-15	72.597 mi
Registration #10	2019-01-15	72.597 mi
Registration #11	2019-01-15	72.597 mi
Registration #12	2019-01-15	72.597 mi
Registration #13	2019-01-15	72.597 mi
Registration #14	2019-01-15	72.597 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70817962