



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Grey
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-02
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-10-06
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	31
Total items failed	3

MOT #16	2022-10-06 13:34
MOT test number	488345731470
Result	✓ Passed
Next expiry date	2023-10-06
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
Advice	Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2021-10-05 12:58
MOT test number	714328495788
Result	✓ Passed
Advice	Condition of front number plate

MOT #14	2021-10-04 14:29
MOT test number	623581415001
Result	✗ Failed
Advice	Condition of front number plate
Fail	Nearside Front Road wheel fixing missing bolt missing (5.2.1 (a) (i))

**MOT #13**

2020-09-16 10:04

MOT test number

799033059432

Result

✓ Passed

Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, but not excessively Both sides (1.1.14 (a) (i))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Inner Tyre has flat spot on inner edge**MOT #12**

2019-10-07 13:13

MOT test number

509883210493

Result

✓ Passed

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Offside Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))**MOT #11**

2018-09-03 10:42

MOT test number

780777862835

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2017-09-20 13:48

MOT test number

936701004475

Result

✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #9** 2016-09-16 16:28**MOT test number** 323631167341**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside wiper slightly split**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear brake binding slightly**MOT #8** 2015-09-10 14:11**MOT test number** 742194280906**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2015-09-09 10:57**MOT test number** 326838794440**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2014-09-04 16:20**MOT test number** 859477344281**Result** ✓ Passed**Notice** N/s/r bump stop perished

**MOT #5** 2013-09-09 16:48**MOT test number** 307152253237**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-09-09 11:14**MOT test number** 905952753296**Result** ✗ Failed**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-08-22 10:57**MOT test number** 669345832279**Result** ✓ Passed**MOT #2** 2011-07-19 14:23**MOT test number** 299730801296**Result** ✓ Passed**MOT #1** 2010-05-18 14:27**MOT test number** 333568330172**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 August 2023

X

MOT

Expired:
6 October 2023

Tax status	Expired at 1 August 2023
Days left	272 days too late
MOT expiry date	6 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	VA07OHR
Plate since	2019-09-29
Current registration	VA07OHR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-06-11
Last registration	2022-10-06
Complete history	See info



Registration #1	2007-06-11	29 mi
Registration #2	2010-05-18	22.283 mi
Registration #3	2011-07-19	37.008 mi
Registration #4	2012-08-22	53.610 mi
Registration #5	2013-09-09	67.965 mi
Registration #6	2013-09-09	67.965 mi
Registration #7	2014-09-04	80.371 mi
Registration #8	2015-09-09	96.700 mi
Registration #9	2015-09-10	96.743 mi
Registration #10	2016-09-09	96.743 mi
Registration #11	2016-09-09	96.743 mi
Registration #12	2016-09-09	96.743 mi
Registration #13	2016-09-09	96.743 mi
Registration #14	2016-09-09	96.743 mi
Registration #15	2016-09-09	96.743 mi
Registration #16	2016-09-09	96.743 mi
Registration #17	2016-09-09	96.743 mi
Registration #18	2016-09-09	96.743 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD B25746