



report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND BLUEHDI VTR PLUS
Colour	Blue
Year of manufacture	2016
Top speed	109 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 2


Date	2021-09-14
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-12
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-06-23
<b>MOT pass rate</b>	83 %
<b>MOT passed</b>	5
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	10
<b>Total items failed</b>	0

**MOT #6** 2023-06-12 08:27**MOT test number** 561405550292**Result** Passed**Next expiry date** 2024-06-23

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre stepped on inner edge
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #5** 2022-06-13 09:18**MOT test number** 747750988632**Result** Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush perished/splitting (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush perished/splitting (5.3.4 (a) (i))

**MOT #4** 2021-06-19 08:37**MOT test number** 480388350490**Result** Passed



<b>MOT #3</b>	2021-06-12 12:14
<b>MOT test number</b>	684238389630
<b>Result</b>	✗ Failed
<b>MAJOR</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

<b>MOT #2</b>	2020-06-12 10:29
<b>MOT test number</b>	745669960518
<b>Result</b>	✓ Passed
<b>Advice</b> Nearside Rear Nail in tyre	
<b>Advice</b> Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
<b>Advice</b> Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

<b>MOT #1</b>	2019-06-01 09:35
<b>MOT test number</b>	964446394926
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
23 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	23 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-24
Last registration	2023-06-12
Complete history	<a href="#">See info</a>



Registration #1	2016-06-24	20 mi
Registration #2	2019-06-01	33.599 mi
Registration #3	2020-06-12	42.850 mi
Registration #4	2021-06-12	50.965 mi
Registration #5	2021-06-19	51.028 mi
Registration #6	2022-06-20	55.277 mi
Registration #7	2022-06-20	55.277 mi
Registration #8	2022-06-20	55.277 mi
Registration #9	2023-06-12	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1320 kg
Max. allowed weight	2175 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBGZ3027909