





report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Silver
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-07-01

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-25
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	8

MOT #16		2023-06-28 14:32
MOT test	number	910233214308
Result		✓ Passed
Next expi	ry date	2024-07-25
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Nail in tyre	

MOT #15	2023-06-28 07:32
MOT test number	382417208771
Result	X Failed
Fail Emissions unable to be completed major exhaust blow (8.2.1.2 (d))	
Fail Offside Headlamp aim too low (4.1.2 (a))	
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Nail in tyre	
Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	

MOT #14	2022-07-26 07:46
MOT test number	137487553339
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #13 2022-07-25 15:50

MOT test number 765532089775

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Very perished (5.2.3 (d) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12 2021-09-24 08:55

MOT test number 587612343676

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2020-09-28 15:04

MOT test number 616741612949

Result

Passed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Both wipers slightly smearing

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2019-09-30 10:41

MOT test number 895326681361

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/13



Pass with rectification

EY58LBN

report date: 2024-03-28

MOT #9	2018-09-19 14:11
MOT test number	746542118383
Result	✓ Passed
MOT #8	2017-08-25 15:39
MOT test number	380676292658
Result	✓ Passed
MOT #7	2016-09-06 09:07
MOT test number	128942827645
Result	✓ Passed
MOT #6	2015-09-10 12:38
MOT test number	937504895411
Result	✓ Passed
Advice Nearside front and offside rear wheels dented	
MOT #5	2014-09-18 11:44
MOT test number	358361464402
Result	✓ Passed
MOT #4	2014-09-18 11:44
MOT test number	857621064287
Result	X Failed
Pass with rectification Offside Stop lamp not working (1.2.1b)	

MOT #3	2013-09-11 13:56
MOT test number	398604053217
Result	✓ Passed

Nearside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/13



MOT #2	2012-09-14 11:05
MOT test number	877318752222
Result	✓ Passed
MOT #1	2011-09-16 12:31
MOT test number	379149251261
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

o met metery	
For how long did the current and previous owner(s) have this FORD? How many owners Check it in the premium report and see all owner registrations. Download the full report	

HEREFE PER STATE OF THE	
HARMAN CO. C.	

	More info >
Plate changes	
Coo in this shock if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-20
Last registration	2023-06-28
Complete history	See info



Registration #1	2008-09-20	15 mi
Registration #2	2011-09-16	17.359 mi
Registration #3	2012-09-14	22.380 mi
Registration #4	2013-09-11	29.478 mi
Registration #5	2014-09-18	36.066 mi
Registration #6	2015-09-10	41.496 mi
Registration #7	2016-09-06	46.264 mi
Registration #8	2017-08-25	47.890 mi
Registration #9	2018-09-19	50.796 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		0.00 es
Registration #16		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 8A48618