



report date: 2024-03-28

## General information

Make	VOLVO
Model	XC70 XC70 D5 SE SPORT
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-07-24
Pictures	28
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-26
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	65
Total items failed	9

MOT #19 2023-07-19 09:48

MOT test number 437924989560

Result ✓ Passed

Next expiry date 2024-07-26

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18 2022-07-27 08:17

MOT test number 302533140061

Result ✓ Passed

- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Inner Play in steering rack inner joint(s) both
- Advice** Offside Front Outer Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #17**

2022-02-10 14:29

**MOT test number**

986832603290

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both bushes. (5.3.4 (a) (i))

**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**Advice** Nearside Front Slight play in drive shaft.

**Advice** Play in steering rack inner joint(s)

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both bushes. (5.3.4 (a) (i))

**MOT #16**

2021-02-04 12:01

**MOT test number**

152976824363

**Result**

✓ Passed

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Play in steering rack inner joint(s)

**Advice** Offside Front Brake hose slightly deteriorated cracked (1.1.12 (b) (ii))

**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Play in steering rack inner joint(s)

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front and rear bushes on track control arm (5.3.4 (a) (i))

**Advice** Nearside Front Inner Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front tyre is scrubbed on outer edge

**MOT #15**

2021-02-03 15:09

**MOT test number**

328991185501

**Result****✗ Failed**

- Advice** Offside Play in steering rack inner joint(s)
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake hose slightly deteriorated cracked (1.1.12 (b) (ii))
- Advice** Nearside Front tyre is scrubbed on outer edge
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Fail** Nearside Front Brake hose excessively deteriorated split (1.1.12 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front and rear bushes on track control arm (5.3.4 (a) (i))
- Advice** Nearside Front Inner Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

**MOT #14** 2020-02-06 15:46**MOT test number** 268298313848**Result** ✓ Passed

- Minor** Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front tyre is scrubbed on outer edge
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front and rear bushes on track control arm (5.3.4 (a) (i))

**MOT #13** 2019-02-08 16:26**MOT test number** 433680079602**Result** ✓ Passed

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #12** 2019-02-08 10:13**MOT test number** 365743673639**Result** ✗ Failed

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #11** 2018-02-07 15:26**MOT test number** 532711109902**Result** ✓ Passed**Advice** Osr 215/65/16 tyre edge wear**MOT #10** 2018-02-07 11:53**MOT test number** 429959539696**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Osr 215/65/16 tyre edge wear**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**MOT #9** 2017-02-08 10:41**MOT test number** 399898868266**Result** ✓ Passed**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside front tyre wearing inner edge**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2017-02-08 10:41**MOT test number** 204275993128**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Upper Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside front tyre wearing inner edge**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-01-08 09:43**MOT test number** 940607903716**Result** ✓ Passed**MOT #6** 2015-01-08 08:39**MOT test number** 968188905022**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-11-06 16:33**MOT test number** 958560113387**Result** ✓ Passed**MOT #4** 2012-12-15 12:06**MOT test number** 625710852370**Result** ✓ Passed



**MOT #3** 2011-12-21 14:08**MOT test number** 587685751374**Result** ✓ Passed**MOT #2** 2011-01-04 13:38**MOT test number** 646004501068**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear brake discs corroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Centre exhaust bracket badly corroded**MOT #1** 2009-12-17 14:11**MOT test number** 503911359314**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
26 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	26 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-01-12
Last registration	2023-07-19
Complete history	<a href="#">See info</a>



Registration #1	2007-01-12	20 mi
Registration #2	2009-12-17	22.386 mi
Registration #3	2011-01-04	28.707 mi
Registration #4	2011-12-21	33.355 mi
Registration #5	2012-12-15	37.568 mi
Registration #6	2013-11-06	40.970 mi
Registration #7	2015-01-08	54.035 mi
Registration #8	2016-01-08	63.509 mi
Registration #9	2017-02-08	79.046 mi
Registration #10	2017-02-08	79.046 mi
Registration #11	2018-02-07	90.730 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi
Registration #20	2019-05-29	95.377 mi
Registration #21	2019-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	432080