



General information

Make	MINI
Model	MINI (R58) ONE D
Colour	Black
Year of manufacture	2011
Top speed	114 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-08-02
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	39
Total items failed	9

MOT #13	2023-08-30 11:54
MOT test number	320225184357
Result	✓ Passed
Next expiry date	2024-09-14

MOT #12	2022-09-02 10:20
MOT test number	768589178016
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #11	2021-09-15 14:06
MOT test number	891605629837
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2021-09-15 08:05

**MOT test number**

477327914677

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9**

2020-12-23 13:05

**MOT test number**

632401987945

**Result****✓ Passed**

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2019-11-09 14:44

**MOT test number**

899238280458

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner & outer edges, 3 mm (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7**

2019-11-09 11:45

**MOT test number**

197391133171

**Result**

✗ Failed

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))

**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Advice** Offside Rear Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner & outer edges, 3 mm (5.2.3 (e))

**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6**

2018-10-20 08:31

**MOT test number**

852924099491

**Result**

✓ Passed

**Advice** Rear tyres perished

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources  
(4.7.1 (b) (i))

**MOT #5** 2017-10-03 14:39**MOT test number** 966145189490**Result** ✓ Passed**Advice** Both rear tyres starting to perish**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Both rear brake discs worn, pitted or scored, but not seriously weakened**Advice** Under trays and engine covers fitted**MOT #4** 2016-11-08 11:34**MOT test number** 291819276830**Result** ✓ Passed**MOT #3** 2016-11-08 11:34**MOT test number** 992738728128**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2015-09-14 10:21**MOT test number** 714873379166**Result** ✓ Passed**MOT #1** 2014-10-13 14:32**MOT test number** 975456684286**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	14 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>LM61EKK</b>
Plate since	2024-03-29
Current registration	<b>LM61EKK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-10-20
Last registration	2023-08-30
Complete history	<a href="#">See info</a>



Registration #1	2011-10-20	28 mi
Registration #2	2014-10-13	25.305 mi
Registration #3	2015-09-14	35.651 mi
Registration #4	2016-11-08	46.838 mi
Registration #5	2016-11-08	46.838 mi
Registration #6	2017-10-03	52.638 mi
Registration #7	2018-10-20	63.083 mi
Registration #8	2019-11-09	67.230 mi
Registration #9	2020-05-20	75.377 mi
Registration #10	2020-05-20	75.377 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70967993