





report date: 2024-03-29

General information

Make	BMW
Model	535 535D SPORT TOURING
Colour	Green
Year of manufacture	-
Top speed	155 mph
0 - 60 mph	6.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	560 Nm at 2.000 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	25.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entr	. 1
EIIU	vт

Lifety 1	
Date	2021-12-12
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #18 2023-06-23 14:58

MOT test number 324987555114

Result X Failed

Advice Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))

DANGEROUS Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

DANGEROUS Rear Suspension system inoperative VEHICLES ON THE FLOOR (5.3.5 (a))

MAJOR Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

DANGEROUS Nearside Rear Road wheel more than one fixing missing 2 MISSING (5.2.1 (a) (ii))

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))

Advice Front Headlamp has a product on the lens but not seriously reducing light output BOTH FROSTED (4.1.4 (b))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17 2021-12-14 15:12

MOT test number 583012272257

Result X Failed

Advice Tpms light on dash

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Electronic stability control warning lamp indicates a fault (7.12 (e))

Advice Suspension light on dash

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #16	2020-08-27 09:50
MOT test number	334789732547
Result	✓ Passed
MOT #15	2019-09-13 16:41
MOT test number	120530943106
Result	✓ Passed
MOT #14	2018-10-09 14:40
MOT test number	621716220438
Result	✓ Passed
****	2017 10 20 10 11
MOT #13	2017-10-28 10:44
MOT test number	306218072957
Result	✓ Passed
MOT #12	2017-10-27 14:25
MOT test number	909938979973
Result	≍ Failed
Advice Offside Rear Tyre worn close to the legal limit 1.8mm (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
MOT #11	2016-10-21 10:23
MOT test number	920081342032

Result	✓ Passed
MOT #10	2015-10-16 13:43
MOT test number	833836296657
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #9 2014-10-18 12:27

MOT test number 569641894295

Result ✓ Passed

MOT #8 2014-10-17 17:02

MOT test number 699760494279

Result X Failed

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #7 2013-10-04 16:59

MOT test number 205767073227

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2012-10-16 11:54

MOT test number 396960092253

Result

Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2011-10-26 16:24

MOT test number 138319691243

Result
✓ Passed

MOT #4 2010-11-25 14:00

MOT test number 441739720485

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #3 2009-11-25 16:53

MOT test number 341559429365

Result
✓ Passed

MOT #2 2008-11-19 10:01

MOT test number 182744128300

Result ✓ Passed

MOT #1 2008-11-17 15:11

MOT test number 564852628307

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

WN55YZH

report date: 2024-03-29

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.

器 ux

More info >

CarCheck.co.uk page 9/12



VN55YZH

report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-11-28
Last registration	2023-06-23
Complete history	See info



Registration #1	2005-11-28	7 mi
Registration #2	2008-11-17	35.099 mi
Registration #3	2008-11-19	35.102 mi
Registration #4	2009-11-25	43.555 mi
Registration #5	2010-11-25	46.310 mi
Registration #6	2011-10-26	49.289 mi
Registration #7	2012-10-16	54.359 mi
Registration #8	2013-10-04	59.872 mi
Registration #9	2014-10-17	65.195 mi
Registration #10	2014-10-18	65.206 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1491 mm
Length	4843 mm
Wheel base	2886 mm
Kerb weight	1830 kg
Max. allowed weight	2315 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number27646016