



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | POLO SE TSI |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 114 mph |
| 0 - 100 km/h | 10.8 seconds |
| 0 - 60 mph | 10.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|------------------------|
| Power | 66 kW / 90 HP / 89 BHP |
| Max. torque | 160 Nm at 1.400 rpm |
| Engine capacity | 1.197 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 107 g/km |
| CO2 label | B |






Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-07-24 |
| Pictures | 19 |
| Listing price | View report |



source: yesauto.com

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-22 |
| Pictures | 20 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-29 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #8 | 2023-07-20 15:51 |
| MOT test number | 296660636558 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-29 |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Vehicles internal headlight adjuster altered to recheck lights |

| | |
|-----------------|--|
| MOT #7 | 2022-07-21 15:56 |
| MOT test number | 366174726248 |
| Result | ✓ Passed |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

| | |
|-----------------|--|
| MOT #6 | 2022-07-21 11:32 |
| MOT test number | 638380835435 |
| Result | ✗ Failed |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Fail | Offside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii)) |

**MOT #5** 2021-07-30 15:06**MOT test number** 567225336102**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Tmps light on but not indicating a fault**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #4** 2021-07-29 12:07**MOT test number** 219448643351**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Nail in tyre**Advice** Tmps light on but not indicating a fault**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2020-10-15 08:16**MOT test number** 590186390632**Result** ✓ Passed**MOT #2** 2019-05-03 09:10**MOT test number** 759625154925**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



| | |
|-----------------|------------------|
| MOT #1 | 2018-05-16 15:22 |
| MOT test number | 797521520673 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 29 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  NV15WBT |
| Plate since | 2019-03-29 |
| Current registration |  NV15WBT |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-07-31 |
| Last registration | 2023-07-20 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-07-31 | 27 mi |
| Registration #2 | 2018-05-16 | 18.042 mi |
| Registration #3 | 2019-05-03 | 25.311 mi |
| Registration #4 | 2020-10-15 | 32.965 mi |
| Registration #5 | 2022-05-20 | 35.277 mi |
| Registration #6 | 2023-07-20 | 35.277 mi |
| Registration #7 | 2023-07-20 | 35.277 mi |
| Registration #8 | 2023-07-20 | 35.277 mi |
| Registration #9 | 2023-07-20 | 35.277 mi |
| Registration #10 | 2023-07-20 | 35.277 mi |
| Registration #11 | 2023-07-20 | 35.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 86% |
| Pedestrian | 41% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1901 mm |
| Height | 1462 mm |
| Length | 3972 mm |
| Wheel base | 2470 mm |
| Kerb weight | 1007 kg |
| Max. allowed weight | 1590 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CJZC437240 |