



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA GS
Colour	Black
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	199 g/km
CO2 label	J






Internet history

Entry 2


Date	2021-11-13
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-06
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	42
Total items failed	0

MOT #15	2023-07-18 17:49
MOT test number	205244855559
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Front Side repeater slightly discoloured both sides (4.4.3 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2022-07-27 15:29

**MOT test number**

929884777867

**Result**

✓ Passed

- Advice** Offside Rear Passenger seat(s) missing at time of test
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Passenger seat(s) missing at time of test
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge tread worn (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner front bush (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13**

2021-07-01 09:41

**MOT test number**

130327930035

**Result**

✓ Passed

**MOT #12** 2020-05-26 12:26**MOT test number** 577599111737**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear wiper worn
- Advice** Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))

**MOT #11** 2020-05-26 10:25**MOT test number** 509621923915**Result** ✗ Failed

- Advice** Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear wiper worn

**MOT #10** 2019-05-28 13:49**MOT test number** 387500918306**Result** ✓ Passed

- Advice** Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2019-05-28 13:03**MOT test number** 590167337458**Result** ✗ Failed**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))**MOT #8** 2018-06-21 13:50**MOT test number** 967328951750**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-06-21 07:50**MOT test number** 471426480051**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6** 2017-06-20 10:33**MOT test number** 613496572072**Result** ✓ Passed

**MOT #5** 2016-06-13 12:37**MOT test number** 904123916148**Result** ✓ Passed**Advice** Nearside Rear tyre wearing on edges slightly**MOT #4** 2015-06-22 08:53**MOT test number** 489893275159**Result** ✓ Passed**Notice** Nearside front & rear tyres worn on edges**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-06-17 11:03**MOT test number** 508188164140**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-06-10 09:02**MOT test number** 797581663174**Result** ✓ Passed**MOT #1** 2012-06-22 13:55**MOT test number** 407894672159**Result** ✓ Passed**Notice** Non obligatory mirror damaged



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
26 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	26 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>GL09GJF</b>
Plate since	2024-03-29
Current registration	<b>GL09GJF</b>
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-25
Last registration	2023-07-18
Complete history	<a href="#">See info</a>



Registration #1	2009-06-25	12 mi
Registration #2	2012-06-22	8.842 mi
Registration #3	2013-06-10	11.623 mi
Registration #4	2014-06-17	15.363 mi
Registration #5	2015-06-22	18.704 mi
Registration #6	2016-06-13	22.069 mi
Registration #7	2017-06-20	27.929 mi
Registration #8	2018-06-21	34.222 mi
Registration #9	2018-06-21	34.222 mi
Registration #10	2019-06-20	35.377 mi
Registration #11	2019-06-20	35.377 mi
Registration #12	2019-06-20	35.377 mi
Registration #13	2019-06-20	35.377 mi
Registration #14	2019-06-20	35.377 mi
Registration #15	2019-06-20	35.377 mi
Registration #16	2019-06-20	35.377 mi
Registration #17	2019-06-20	35.377 mi
Registration #18	2019-06-20	35.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2168 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	J3 8 289765