



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	A-CLASS A180 CDI ELEGANCE SE
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history****MOT #22** 2022-06-24 14:46**MOT test number** 149828121459**Result** ✓ Passed**Next expiry date** 2023-06-23**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #21** 2022-06-07 08:33**MOT test number** 577340226747**Result** ✗ Failed**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Nearside Brake pipe excessively corroded Front to rear (1.1.11 (c))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #20** 2021-06-04 12:21**MOT test number** 889199025683**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Handbrake high

**MOT #19** 2021-06-04 11:22**MOT test number** 282752277293**Result** ✗ Failed**Advice** Handbrake high**MAJOR** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #18** 2020-06-16 15:38**MOT test number** 424889566039**Result** ✓ Passed**Advice** Hand brake leaver slightly high**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #17** 2019-06-20 10:44**MOT test number** 326458826857**Result** ✓ Passed**MOT #16** 2019-02-28 16:48**MOT test number** 329531878770**Result** ✓ Passed**MOT #15** 2019-02-22 11:18**MOT test number** 623564031772**Result** ✗ Failed**MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e))**MAJOR** Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #14** 2018-02-27 09:37**MOT test number** 534502710577**Result** ✓ Passed**MOT #13** 2017-02-17 11:23**MOT test number** 935917027968**Result** ✓ Passed**MOT #12** 2016-03-11 11:14**MOT test number** 379503526437**Result** ✓ Passed**MOT #11** 2016-03-04 16:10**MOT test number** 289860361005**Result** ✓ Passed**MOT #10** 2016-02-27 16:58**MOT test number** 282767433639**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #9** 2015-09-18 12:22**MOT test number** 609835059106**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2014-09-08 12:02**MOT test number** 226911454246**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2013-09-03 13:51**MOT test number** 736326443291**Result** ✓ Passed**MOT #6** 2013-08-31 11:50**MOT test number** 299303043232**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2012-08-28 12:19**MOT test number** 339791542461**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2011-08-18 17:40**MOT test number** 349850731468**Result** ✓ Passed



MOT #3	2011-08-18 10:22
MOT test number	447510931257
Result	✗ Failed
Fail	Offside Headlamp aim too high (1.8)
Fail	Nearside Headlamp aim too high (1.8)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Registration plate lamp not working (1.1.C.1d)

MOT #2	2010-09-17 12:13
MOT test number	502390460292
Result	✓ Passed

MOT #1	2009-08-28 11:11
MOT test number	623180749251
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Plastic covers fitted to underneath of car making it hard to complete examination



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 BF56BGU
Plate since	2024-03-28
Current registration	 BF56BGU
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-05
Last registration	2022-06-24
Complete history	See info



Registration #1	2006-09-05	7 mi
Registration #2	2009-08-28	21.470 mi
Registration #3	2010-09-17	27.765 mi
Registration #4	2011-08-18	32.535 mi
Registration #5	2011-08-18	32.535 mi
Registration #6	2012-08-28	40.124 mi
Registration #7	2013-08-31	49.262 mi
Registration #8	2013-09-03	49.291 mi
Registration #9	2014-09-08	53.854 mi
Registration #10	2015-09-18	58.434 mi
Registration #11	2016-02-27	59.948 mi
Registration #12	2016-03-04	59.950 mi
Registration #13	2016-03-04	59.950 mi
Registration #14	2016-03-04	59.950 mi
Registration #15	2016-03-04	59.950 mi
Registration #16	2016-03-04	59.950 mi
Registration #17	2016-03-04	59.950 mi
Registration #18	2016-03-04	59.950 mi
Registration #19	2016-03-04	59.950 mi
Registration #20	2016-03-04	59.950 mi
Registration #21	2016-03-04	59.950 mi
Registration #22	2016-03-04	59.950 mi
Registration #23	2016-03-04	59.950 mi
Registration #24	2016-03-04	59.950 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1764 mm
Height	1593 mm
Length	3838 mm
Wheel base	2568 mm
Kerb weight	1345 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	64094030046199