



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Grey
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





MOT history

MOT expiry date	2024-09-18
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	4

MOT #16 2023-09-14 11:57

MOT test number 114267189625

Result ✓ Passed

Next expiry date 2024-09-18

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15 2023-09-14 10:28

MOT test number 531498597315

Result ✗ Failed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Fail Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #14** 2022-09-14 12:21**MOT test number** 804462955306**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #13** 2021-09-13 12:11**MOT test number** 251702478510**Result** ✓ Passed**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12** 2020-09-14 14:20**MOT test number** 182426153060**Result** ✓ Passed**MOT #11** 2019-09-09 08:20**MOT test number** 235471349237**Result** ✓ Passed**MOT #10** 2018-09-14 07:46**MOT test number** 377720971689**Result** ✓ Passed**MOT #9** 2018-09-13 12:02**MOT test number** 771750211751**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**MOT #8** 2017-09-06 13:04**MOT test number** 882662764876**Result** ✓ Passed

**MOT #7** 2017-09-06 13:04**MOT test number** 998095527536**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working bulb fitted (1.1.C.1d)**MOT #6** 2016-09-10 08:35**MOT test number** 333491567100**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #5** 2015-09-12 10:51**MOT test number** 375230231189**Result** ✓ Passed**MOT #4** 2014-09-19 09:06**MOT test number** 669382664204**Result** ✓ Passed**MOT #3** 2013-07-31 11:14**MOT test number** 209842113239**Result** ✓ Passed**Notice** Rear tyres cracking**Notice** Offside front tyre getting low



MOT #2	2013-07-29 17:22
MOT test number	358750313225
Result	✗ Failed
Notice	Rear tyres cracking
Fail	Fuel tank leaking (7.2.3)
Notice	Offside front tyre getting low

MOT #1	2012-07-27 10:36
MOT test number	977199302227
Result	✓ Passed
Notice	Nearside front brake disc scored
Notice	Offside front brake disc scored



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 September 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LB09JWK
Plate since	2024-03-29
Current registration	 LB09JWK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-08-11
Last registration	2023-09-14
Complete history	See info



Registration #1	2009-08-11	18 mi
Registration #2	2012-07-27	19.512 mi
Registration #3	2013-07-29	25.337 mi
Registration #4	2013-07-31	25.337 mi
Registration #5	2014-09-19	27.953 mi
Registration #6	2015-09-12	31.901 mi
Registration #7	2016-09-10	35.486 mi
Registration #8	2017-09-06	39.239 mi
Registration #9	2017-09-06	39.239 mi
Registration #10	2019-09-06	39.239 mi
Registration #11	2019-09-06	39.239 mi
Registration #12	2019-09-06	39.239 mi
Registration #13	2019-09-06	39.239 mi
Registration #14	2019-09-06	39.239 mi
Registration #15	2019-09-06	39.239 mi
Registration #16	2019-09-06	39.239 mi
Registration #17	2019-09-06	39.239 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD486282