



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 VT
Colour	Red
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-31
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	25
Total items failed	14

MOT #17	2022-10-03 11:00
MOT test number	434701859568
Result	✓ Passed
Next expiry date	2023-10-31

MOT #16	2022-10-01 11:44
MOT test number	263959297606
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Rear Exhaust has a major leak of exhaust gases joint (6.1.2 (a))

MOT #15	2021-10-28 10:02
MOT test number	425266106703
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Play in steering rack inner joint(s)

**MOT #14**

2021-10-27 09:25

MOT test number

381640624433

Result**✗ Failed**

- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13

2020-10-31 10:40

MOT test number

221484199208

Result**✓ Passed**

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #12

2020-10-30 16:35

MOT test number

515453817151

Result**✗ Failed**

- Fail** Nearside Headlamp aim not tested (4.1.2 (b))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Exhaust fumes entering cabin (6.1.2 (b) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))



MOT #11	2019-11-01 10:40
----------------	------------------

MOT test number	183182167414
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2018-10-25 12:05
----------------	------------------

MOT test number	480511608403
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
---------------	---

Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
---------------	--

MOT #9	2017-10-20 09:49
---------------	------------------

MOT test number	325515961603
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2016-10-14 10:44
---------------	------------------

MOT test number	580445852865
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
---------------	--

Advice	Exhaust hanger broken but secure
---------------	----------------------------------

MOT #7	2015-10-30 09:15
---------------	------------------

MOT test number	321551753945
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #6** 2014-10-31 15:14**MOT test number** 457674904389**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2014-10-31 15:14**MOT test number** 637204704300**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-08-08 13:49**MOT test number** 369970123244**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-08-08 10:59**MOT test number** 327450423253**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2012-08-11 09:59
MOT test number	638794622203
Result	✓ Passed

MOT #1	2012-08-11 09:59
MOT test number	527374522298
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Front constant velocity joint is insecure (2.5.C.1b)	



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-08-15
Last registration	2022-10-03
Complete history	See info



Registration #1	2009-08-15	23 mi
Registration #2	2012-08-11	20.927 mi
Registration #3	2013-08-08	27.834 mi
Registration #4	2013-08-08	27.834 mi
Registration #5	2014-10-31	47.486 mi
Registration #6	2015-10-30	46.555 mi
Registration #7	2016-10-14	55.507 mi
Registration #8	2017-10-20	57.966 mi
Registration #9	2018-10-25	60.531 mi
Registration #10	2019-10-25	61.557 mi
Registration #11	2019-10-25	61.557 mi
Registration #12	2019-10-25	61.557 mi
Registration #13	2019-10-25	61.557 mi
Registration #14	2019-10-25	61.557 mi
Registration #15	2019-10-25	61.557 mi
Registration #16	2019-10-25	61.557 mi
Registration #17	2019-10-25	61.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	956 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5123324