



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Black
Year of manufacture	2007
Top speed	147 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 2


Date	2022-04-01
Pictures	17
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-11
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-11
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	27
Total items failed	16

MOT #20	2023-08-03 08:39
MOT test number	638982840521
Result	✓ Passed
Next expiry date	2024-08-11

MOT #19	2022-08-08 16:38
MOT test number	472170140361
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Brake disc worn, but not excessively All four (1.1.14 (a) (i))

MOT #18	2021-08-12 09:49
MOT test number	895852257849
Result	✓ Passed

MOT #17	2020-10-08 11:38
MOT test number	975813059054
Result	✓ Passed

**MOT #16** 2020-10-08 09:32**MOT test number** 433221989629**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #15** 2019-10-08 13:27**MOT test number** 731281535975**Result** ✓ Passed**MOT #14** 2019-10-08 11:44**MOT test number** 733838030308**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #13** 2018-10-20 12:28**MOT test number** 933579972576**Result** ✓ Passed**Advice** Front and rear brake discs worn**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Front and rear suspension components have surface corrosion**Advice** Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

**MOT #12**

2018-10-04 11:01

MOT test number

637574822174

Result**✗ Failed**

- Advice** Front Play in steering rack inner joint(s) X2
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened X2 (1.1.14 (a) (ii))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge X2 NSR/OSR VERY CLOSE TO LEGAL LIMIT 2mm (5.2.3 (e))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened X2 (1.1.14 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 39% RECOMMEND BRAKE SERVICE (1.2.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn REAR BJ, MARKED IN YELLOW. (5.3.4 (a) (i))

MOT #11

2017-10-04 09:45

MOT test number

365183882664

Result**✓ Passed**

- Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Both rear brake hoses slightly deteriorated
- Advice** Front and rear suspension components slightly corroded



MOT #10	2016-10-08 09:19
MOT test number	393563464030
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2016-10-07 11:52
MOT test number	462568032334
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #8	2016-10-05 14:46
MOT test number	595424978988
Result	✗ Failed
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
Fail	Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
Fail	Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #7	2015-08-03 15:36
MOT test number	849875815210
Result	✓ Passed

Notice N/s/f perished

Advice Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt
(2.4.G.2)

**MOT #6** 2015-08-03 10:25**MOT test number** 328395215453**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-02-27 18:27**MOT test number** 299568754038**Result** ✓ Passed**MOT #4** 2014-02-27 18:27**MOT test number** 545058654022**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2013-02-08 18:43**MOT test number** 226529833046**Result** ✓ Passed**MOT #2** 2012-03-05 11:02**MOT test number** 946555062022**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2011-02-03 09:02
MOT test number	516394631079
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
11 August 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	11 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-28
Last registration	2023-08-03
Complete history	See info



Registration #1	2007-09-28	21 mi
Registration #2	2011-02-03	24.759 mi
Registration #3	2012-03-05	30.233 mi
Registration #4	2013-02-08	35.281 mi
Registration #5	2014-02-27	41.377 mi
Registration #6	2015-08-03	50.222 mi
Registration #7	2015-08-03	50.233 mi
Registration #8	2016-10-05	57.353 mi
Registration #9	2016-10-07	57.359 mi
Registration #10	2016-10-08	57.376 mi
Registration #11	2017-10-04	65.962 mi
Registration #12	2018-05-22	75.377 mi
Registration #13	2018-05-22	75.377 mi
Registration #14	2018-05-22	75.377 mi
Registration #15	2018-05-22	75.377 mi
Registration #16	2018-05-22	75.377 mi
Registration #17	2018-05-22	75.377 mi
Registration #18	2018-05-22	75.377 mi
Registration #19	2018-05-22	75.377 mi
Registration #20	2018-05-22	75.377 mi
Registration #21	2018-05-22	75.377 mi
Registration #22	2018-05-22	75.377 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530941442