



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Blue
Year of manufacture	2003
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	157 BHP
Max. torque	200 Nm at 4.100 rpm
Engine capacity	2.099 cc
Cylinders	6
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.7 mpg
CO2 emission	218 g/km
CO2 label	K





Internet history

Entry 2


Date	2021-07-13
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-30
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-24
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	40
Total items failed	2

MOT #23 2024-01-24 12:19

MOT test number 621250219354

Result ✓ Passed

Next expiry date 2025-01-24

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Central Brake pipe corroded, covered in grease or other material both front to rear pipes (1.1.11 (c))

MOT #22 2024-01-15 10:36

MOT test number 970067701032

Result ✗ Failed

MAJOR Offside Front Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MAJOR Nearside Front Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Central Brake pipe corroded, covered in grease or other material both front to rear pipes (1.1.11 (c))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #21** 2023-01-25 09:20**MOT test number** 238299515244**Result** ✓ Passed**MOT #20** 2023-01-20 12:15**MOT test number** 765827191152**Result** ✗ Failed**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Offside Brake pipe excessively corroded (1.1.11 (c))**MOT #19** 2021-07-23 10:33**MOT test number** 145200247377**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #18** 2020-07-08 12:36**MOT test number** 899511720356**Result** ✓ Passed**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))



MOT #17	2019-07-08 13:27
MOT test number	424133047806
Result	✓ Passed
Advice	Central Brake pipe corroded, covered in grease or other material main x2 (1.1.11 (c))

MOT #16	2019-07-05 09:56
MOT test number	681366767288
Result	✗ Failed
Advice	Central Brake pipe corroded, covered in grease or other material main x2 (1.1.11 (c))
MAJOR	Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))
MAJOR	Offside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner sill. (5.3.6 (a) (i))

MOT #15	2018-07-10 10:50
MOT test number	486511840009
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material MAIN PIPES FRONT TO REAR (1.1.11 (c))

MOT #14	2017-07-11 09:31
MOT test number	606482234702
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit TYRE WORN ON INNER AND OUTER EDGE (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit TYRE WORN ON INNER AND OUTER EDGE (4.1.E.1)

MOT #13	2016-06-28 08:03
MOT test number	383547678751
Result	✓ Passed
Advice	Brake fluid reservoir cap split
Advice	Nearside Brake pipe slightly corroded Front to rear (3.6.B.2c)

**MOT #12** 2015-07-15 09:22**MOT test number** 757606895120**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Notice** Nail in offside rear tyre**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-07-15 13:15**MOT test number** 377356194151**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #10** 2013-07-05 11:19**MOT test number** 909366483112**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #9** 2012-07-10 11:19**MOT test number** 409862692130**Result** ✓ Passed**MOT #8** 2012-07-10 11:19**MOT test number** 185852692149**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #7** 2011-07-06 15:04**MOT test number** 575187181182**Result** ✓ Passed**MOT #6** 2011-07-06 09:58**MOT test number** 406357981131**Result** ✗ Failed**Fail** Nearside Rear Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #5** 2010-07-12 16:22**MOT test number** 121183190167**Result** ✓ Passed**MOT #4** 2009-07-08 10:27**MOT test number** 292069089155**Result** ✓ Passed**MOT #3** 2008-07-09 12:44**MOT test number** 671241698134**Result** ✓ Passed**MOT #2** 2007-07-19 10:32**MOT test number** 810610707204**Result** ✓ Passed**MOT #1** 2006-09-08 09:30**MOT test number** 291331656255**Result** ✓ Passed**Notice** Engine oil below minimum**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	DU53BTO
Plate since	2019-03-29
Current registration	DU53BTO
Plate since	2019-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-09-10
Last registration	2024-01-24
Complete history	See info



Registration #1	2003-09-10	28 mi
Registration #2	2006-09-08	26.295 mi
Registration #3	2007-07-19	32.749 mi
Registration #4	2008-07-09	37.200 mi
Registration #5	2009-07-08	41.208 mi
Registration #6	2010-07-12	44.835 mi
Registration #7	2011-07-06	48.193 mi
Registration #8	2011-07-06	48.193 mi
Registration #9	2012-07-10	52.407 mi
Registration #10	2013-07-05	56.119 mi
Registration #11	2014-07-15	59.901 mi
Registration #12	2015-07-15	63.544 mi
Registration #13	2016-06-28	66.957 mi
Registration #14	2016-06-28	66.957 mi
Registration #15	2016-06-28	66.957 mi
Registration #16	2016-06-28	66.957 mi
Registration #17	2016-06-28	66.957 mi
Registration #18	2016-06-28	66.957 mi
Registration #19	2016-06-28	66.957 mi
Registration #20	2016-06-28	66.957 mi
Registration #21	2016-06-28	66.957 mi
Registration #22	2016-06-28	66.957 mi
Registration #23	2016-06-28	66.957 mi
Registration #24	2016-06-28	66.957 mi
Registration #25	2016-06-28	66.957 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1450 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	374641430YB