



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Grey
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-01
Pictures	41
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-28
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	40
Total items failed	7

MOT #142023-07-14 10:25

MOT test number872716158195

Result✓ Passed

Next expiry date2024-07-28

- Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Rear Exhaust mounting defective (6.1.2 (a))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2022-07-16 11:39

MOT test number

149685380011

Result

✓ Passed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front to rear surface rust
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2022-07-11 14:32

MOT test number

653382859784

Result

✗ Failed

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Obligatory mirror missing (3.3 (a))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Front to rear surface rust
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2021-07-29 13:31**MOT test number** 299797842298**Result** ✓ Passed

- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Coil spring mounting corroded but not seriously weakened o/s+n/s (5.3.1 (b) (i))

MOT #10 2020-07-14 10:29**MOT test number** 949466308740**Result** ✓ Passed**MOT #9** 2019-08-15 08:16**MOT test number** 164817450963**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-08-09 13:45**MOT test number** 514432346868**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2018-08-09 09:23**MOT test number** 899129488338**Result** ✗ Failed**Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-07-31 09:25**MOT test number** 901215620383**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2016-08-15 11:36**MOT test number** 231525701237**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-08-15 08:47**MOT test number** 770072057504**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-08-19 10:45**MOT test number** 461277240274**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Under trays fit**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2014-08-08 09:28**MOT test number** 586530324275**Result** ✓ Passed**MOT #1** 2013-08-21 09:50**MOT test number** 758913833258**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
28 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	28 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-12
Last registration	2023-07-14
Complete history	See info



Registration #1	2010-03-12	24 mi
Registration #2	2013-08-21	35.300 mi
Registration #3	2014-08-08	44.936 mi
Registration #4	2015-08-19	54.238 mi
Registration #5	2016-08-15	61.492 mi
Registration #6	2016-08-15	61.492 mi
Registration #7	2017-07-31	66.655 mi
Registration #8	2018-08-09	73.552 mi
Registration #9	2019-08-09	80.449 mi
Registration #10	2020-08-09	87.346 mi
Registration #11	2021-08-09	94.243 mi
Registration #12	2022-08-09	101.140 mi
Registration #13	2023-07-14	108.037 mi
Registration #14	2023-07-14	108.037 mi
Registration #15	2023-07-14	108.037 mi
Registration #16	2023-07-14	108.037 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AL38072