



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	White
Year of manufacture	2010
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-06-12
Pictures	27
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-24
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	21
Total items failed	11

MOT #16	2023-05-18 14:47
MOT test number	514974738042
Result	✓ Passed
Next expiry date	2024-05-24
Advice	Rear Coil spring corroded both rear springs (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-05-18 10:53
MOT test number	787182294206
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Coil spring corroded both rear springs (5.3.1 (b) (i))

MOT #14	2022-05-09 09:35
MOT test number	342265105011
Result	✓ Passed
Advice	Front brake discs corroded

**MOT #13** 2021-05-25 15:37**MOT test number** 852353206640**Result** ✓ Passed**MOT #12** 2021-05-13 15:31**MOT test number** 849705992502**Result** ✗ Failed

- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Both daytime running lights not working
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Rear Exhaust system insecure (6.1.2 (a))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #11** 2020-11-16 11:54**MOT test number** 526915865807**Result** ✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened corroded/pitted/scored (1.1.14 (a) (ii))
- Advice** Rear silencer casing corroded
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front drl not working

**MOT #10** 2019-11-22 09:34**MOT test number** 521021581207**Result** ✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted/lipped (1.1.14 (a) (ii))

**MOT #9** 2018-10-08 09:02**MOT test number** 751265465159**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2017-08-03 12:08**MOT test number** 814190492930**Result** ✓ Passed**MOT #7** 2017-08-03 10:18**MOT test number** 877929182397**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2016-08-01 15:32**MOT test number** 678163566248**Result** ✓ Passed**Advice** Offside day light running lamp not working**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #5** 2016-08-01 14:15**MOT test number** 472528314507**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside day light running lamp not working**Fail** Offside Headlamp aim too low (1.8)**MOT #4** 2015-07-07 09:55**MOT test number** 995928285199**Result** ✓ Passed**MOT #3** 2015-07-06 17:51**MOT test number** 746127085158**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2014-12-29 12:14**MOT test number** 278503764358**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Light corrosion to exhaust back box**MOT #1** 2013-12-20 10:20**MOT test number** 468554053433**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
24 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	24 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-12-29
Last registration	2023-05-18
Complete history	<a href="#">See info</a>



Registration #1	2010-12-29	20 mi
Registration #2	2013-12-20	22.971 mi
Registration #3	2014-12-29	27.918 mi
Registration #4	2015-07-06	30.467 mi
Registration #5	2015-07-07	30.467 mi
Registration #6	2016-08-01	40.483 mi
Registration #7	2016-08-01	40.483 mi
Registration #8	2017-08-03	44.849 mi
Registration #9	2017-08-03	44.849 mi
Registration #10	2018-05-29	55.377 mi
Registration #11	2018-05-29	55.377 mi
Registration #12	2018-05-29	55.377 mi
Registration #13	2018-05-29	55.377 mi
Registration #14	2018-05-29	55.377 mi
Registration #15	2018-05-29	55.377 mi
Registration #16	2018-05-29	55.377 mi
Registration #17	2018-05-29	55.377 mi
Registration #18	2018-05-29	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6013020