



report date: 2024-03-29

General information

Make	KIA
Model	RIO 2
Colour	Silver
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-21
Pictures	8
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-12-15
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	48
Total items failed	2

MOT #12	2023-12-16 17:32
MOT test number	803796859283
Result	✓ Passed
Next expiry date	2024-12-15
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11	2022-08-17 09:16
MOT test number	539311580043
Result	✓ Passed
Advice	Front Anti-roll bar linkage corroded but not seriously weakened both (5.3.3 (b) (i))
Advice	Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

MOT #10	2021-08-11 14:26
MOT test number	720287424390
Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front backplate deteriorated
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front backplate deteriorated
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2021-08-11 08:48**MOT test number** 574416265273**Result** ✗ Failed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front backplate deteriorated
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front backplate deteriorated

MOT #8 2020-09-10 16:32**MOT test number** 609357219897**Result** ✓ Passed

- Advice** Offside Front Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust mounting defective mountings corroded. (6.1.2 (a))
- Advice** Exhaust jointing flanges corroded.
- Advice** Offside Rear brake back plate corroded and missing.
- Advice** Front Tyre slightly damaged/cracking or perishing tyres both wearing and splitting in inner tread (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake pipe corroded, covered in grease or other material both front to rear brake pipes (inside plastic sheilding) slight corrosion. can not inspect fully due to covers. (1.1.11 (c))
- Advice** Steering and suspension componants all corroded slighty but ok at present.
- Advice** Tyre slightly damaged/cracking or perishing both rear tyres cracking and splitting in inner tread and tread low on n/s/r (5.2.3 (d) (ii))

**MOT #7**

2020-09-03 15:29

MOT test number

250875606207

Result**✗ Failed****Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Steering and suspension components all corroded slightly but ok at present.**MAJOR** Nearside Front Brake pipe excessively corroded to rear front section near bulk head (1.1.11 (c))**Advice** Front Tyre slightly damaged/cracking or perishing tyres both wearing and splitting in inner tread (5.2.3 (d) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps both (4.7.2 (a))**Advice** Brake pipe corroded, covered in grease or other material both front to rear brake pipes (inside plastic sheilding) slight corrosion. can not inspect fully due to covers. (1.1.11 (c))**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Exhaust jointing flanges corroded.**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear brake back plate corroded and missing.**DANGEROUS** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**MAJOR** Offside Front Brake pipe excessively corroded to rear section front near bulk head (1.1.11 (c))**Advice** Tyre slightly damaged/cracking or perishing both rear tyres cracking and splitting in inner tread and tread low on n/s/r (5.2.3 (d) (ii))**Advice** Offside Front Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Exhaust mounting defective mountings corroded. (6.1.2 (a))

**MOT #6** 2019-09-03 13:51**MOT test number** 231570936808**Result** ✓ Passed**Advice** Front Items removed from driver's view prior to test**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2018-08-16 11:56**MOT test number** 313447526898**Result** ✓ Passed**MOT #4** 2017-09-01 12:02**MOT test number** 618508627759**Result** ✓ Passed**MOT #3** 2016-08-12 10:57**MOT test number** 680553732430**Result** ✓ Passed**MOT #2** 2016-08-12 10:57**MOT test number** 820227932997**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper blade insecure (8.2.2)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)



MOT #1	2015-08-25 11:07
MOT test number	413664961981
Result	✓ Passed
Advice	Rear whiper blade
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 December 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-04
Last registration	2023-12-16
Complete history	See info



Registration #1	2012-09-04	26 mi
Registration #2	2015-08-25	25.822 mi
Registration #3	2016-08-12	35.035 mi
Registration #4	2016-08-12	35.035 mi
Registration #5	2017-09-01	44.747 mi
Registration #6	2018-08-16	51.503 mi
Registration #7	2019-09-03	60.819 mi
Registration #8	2020-09-03	65.277 mi
Registration #9	2021-09-03	65.277 mi
Registration #10	2022-09-03	65.277 mi
Registration #11	2023-09-03	65.277 mi
Registration #12	2024-09-03	65.277 mi
Registration #13	2025-09-03	65.277 mi
Registration #14	2026-09-03	65.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1211 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LACP098543