





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VERSO D-4D T3
Colour	Silver
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	Н





MOT history

MOT expiry date	2021-11-16
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #12	2020-11-17 16:09
MOT test number	864462937009
Result	✓ Passed
Next expiry date	2021-11-16
Advice Offside Rear Vehicle structure is corroded but structural rigidity is not (c) (i))	significantly reduced (6.1.1
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	
Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn	both side (5.1.2 (b) (i))

MOT #11

MOT #11	2020-11-17 14:31
MOT test number	566356335987
Result	🗙 Failed
Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both s	ide (5.1.2 (b) (i))
Fail Rear Position lamp adversely affected by the operation of another lamp all lights	s (4.2.3 (c))
Advice Offside Rear Vehicle structure is corroded but structural rigidity is not signific (c) (i))	cantly reduced (6.1.1
Fail Front Headlamp are incorrectly positioned both side head light (4.1.4 (a))	
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not signi (6.1.1 (c) (i))	ificantly reduced

MOT #10	2019-05-16 14:54
MOT test number	555312768330
Result	✓ Passed





MOT #9	2018-05-11 08:05
MOT test number	627631705733
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	

MOT #8	2017-05-03 15:29
MOT test number	652334224221
Result	✓ Passed

MOT #7	2016-04-28 08:49
MOT test number	636656325718
Result	✓ Passed
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 26% (3.7.B.5b)	
Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear	view (8.1.2a)

MOT #6		2014-12-04 17:06
MOT test	number	955458034382
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A'	(8.3.1d)
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Notice	Items removed from driver's view prior to test	



MOT #5	2014-12-04 14:43
MOT test number	338938034360
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Notice Under-trays fitted obscuring some underside components	
Fail Offside Headlamp aim too low (1.8)	
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' ((8.3.1d)
Notice Items removed from driver's view prior to test	

MOT #4	2013-10-17 17:00
MOT test number	218280393279
Result	✓ Passed
МОТ #3	2012-12-03 14:51
MOT test number	499718232326
Result	✓ Passed
MOT #2	2011-11-19 13:24
MOT test number	407383421338
Result	✓ Passed
MOT #1	2010-11-15 18:18

	2010-11-13 10.10
MOT test number	630879910346
Result	✓ Passed

AP57YVB

report date: 2024-03-29



Tax & MOT check

X Untaxed Tax expired: 5 February 2021	X MOT Expired: 16 November 2021
Tax status	Expired at 5 February 2021
Days left	1179 days too late
MOT expiry date	16 November 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-11-26
Last registration	2020-11-17
Complete history	See info



Registration #1	2007-11-26	16 mi
Registration #2	2010-11-15	92.669 mi
Registration #3	2011-11-19	107.409 mi
Registration #4	2012-12-03	111.845 mi
Registration #5	2013-10-17	116.363 mi
Registration #6	2014-12-04	130.413 mi
Registration #7	2014-12-04	130.420 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.707 mi
Registration #12		11.777 esi
Registration #13		11.227 mi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg
Additional information	
Fuel tank capacity	60
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles	2
Engine number	2AD521824