



LX64JKE

report date: 2024-03-28

General information

Make	MINI
Model	COOPER COOPER SD
Colour	Black
Year of manufacture	-
Top speed	141 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	360 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2023-01-13
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2022-02-23
Pictures	1
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

**MOT history**

MOT #8	2023-01-20 15:31
MOT test number	353979059068
Result	✓ Passed
Next expiry date	2024-01-19

MOT #7	2022-06-09 13:53
MOT test number	410980847764
Result	✓ Passed

Advice Nearside Rear Nail in tyre

MOT #6	2022-01-07 15:47
MOT test number	169456865035
Result	✓ Passed

MOT #5	2022-01-07 09:49
MOT test number	675287719480
Result	✗ Failed

Fail Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #4** 2021-01-27 10:58**MOT test number** 579212405166**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #3** 2019-07-09 13:57**MOT test number** 194959042809**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #2** 2018-10-13 07:47**MOT test number** 833548874037**Result** ✓ Passed**MOT #1** 2017-10-05 10:19**MOT test number** 453025717110**Result** ✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	LX64JKE
Plate since	2019-09-28
Current registration	LX64JKE
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-07
Last registration	2023-01-20
Complete history	See info



Registration #1	2014-10-07	23 mi
Registration #2	2017-10-05	20.786 mi
Registration #3	2018-10-13	30.773 mi
Registration #4	2019-07-09	37.561 mi
Registration #5	2021-01-27	50.059 mi
Registration #6	2022-01-07	61.980 mi
Registration #7	2023-01-20	61.980 mi
Registration #8	2023-01-20	61.980 mi
Registration #9	2023-01-20	61.980 mi
Registration #10	2023-01-20	61.980 mi
Registration #11	2023-01-20	61.980 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1235 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	78399073