




report date: 2024-12-04

General information

Make	MINI
Model	COOPER D LONDON 2012 EDITION
Colour	Silver
Year of manufacture	2012
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A



## Internet history

### Entry 3

Date	2024-03-17
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)

### Entry 2

Date	2023-12-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](http://carcraft.co.uk)

### Entry 1

Date	2023-10-13
Pictures	4
Listing price	<a href="#">View report</a>



**Video viewing**  
Book a video viewing with one of our team.  
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)



**Click & Deliver**  
Complete your deal online or by phone.  
Then arrange for the sanitised vehicle to be delivered to you.

[Visit our website for more info](#)



**JORDAN MOTOR HOUSE**  
AWAITING PHOTOS

07737196121    [jordanmotorhouse@co](mailto:jordanmotorhouse@co)



**Click & Collect**  
Start your deal online or by phone.  
When you visit, our safe and clean environment has been designed for a contactless viewing and handover with you.

[Visit our website for more info](#)



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2024-10-31
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	42
Total items failed	11

MOT #12 2023-11-01 15:55

MOT test number 978037984472

Result ✔ Passed

Next expiry date 2024-10-31

- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear subframe undersealed
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front and rear brake pad wear sensors damaged
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #11 2023-10-31 14:33

MOT test number 290885931142

Result ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front and rear brake pad wear sensors damaged
- Fail** Nearside Rear Anti-lock braking system wiring excessively damaged (1.6 (d))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Rear Brake hose excessively stretched (1.1.12 (b) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #10 2022-05-30 16:18

MOT test number 609646274415

Result ✓ Passed

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))



MOT #9 2021-04-09 15:46

MOT test number 920796310177

Result ✔ Passed

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8 2021-04-09 09:59

MOT test number 815050760408

Result ✘ Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))



<b>MOT #7</b>	2019-07-25 13:42
<b>MOT test number</b>	584832764898
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2018-05-12 12:19
<b>MOT test number</b>	115961650260
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
<b>Advice</b>	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

<b>MOT #5</b>	2017-05-25 08:34
<b>MOT test number</b>	571975963512
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #4</b>	2017-05-25 08:34
<b>MOT test number</b>	597269753166
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp aim too low (1.8)
<b>Advice</b>	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
<b>Pass with rectification</b>	Offside Headlamp aim too high (1.8)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #3** 2016-04-14 10:25

**MOT test number** 253825640573

**Result** ✔ Passed

**MOT #2** 2016-04-14 10:25

**MOT test number** 946799272324

**Result** ✘ Failed

**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #1** 2015-04-17 14:23

**MOT test number** 216777905422

**Result** ✔ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 May 2025

✗  
**MOT**

**Expired:**  
31 October 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	102
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable




**Damage history**

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra MINI salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>GV12OVF</b>
Plate since	2019-09-29
Current registration	<b>GV12OVF</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	16
<b>First mileage registration</b>	2012-06-29
<b>Last registration</b>	2023-11-01
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2012-06-29	25 mi
<b>Registration #2</b>	2015-04-17	8.006 mi
<b>Registration #3</b>	2016-04-14	16.311 mi
<b>Registration #4</b>	2016-04-14	16.311 mi
<b>Registration #5</b>	2017-05-25	24.803 mi
<b>Registration #6</b>	2017-05-25	24.803 mi
<b>Registration #7</b>	2018-05-12	32.626 mi
<b>Registration #8</b>	2019-07-25	36.074 mi
<b>Registration #9</b>	2019-07-25	36.074 mi
<b>Registration #10</b>	2019-07-25	36.074 mi
<b>Registration #11</b>	2019-07-25	36.074 mi
<b>Registration #12</b>	2019-07-25	36.074 mi
<b>Registration #13</b>	2019-07-25	36.074 mi
<b>Registration #14</b>	2019-07-25	36.074 mi
<b>Registration #15</b>	2019-07-25	36.074 mi
<b>Registration #16</b>	2019-07-25	36.074 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	70548105