





report date: 2024-03-28

## General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



GN15WYB report date: 2024-03-28

# Internet history

#### Entry 3

Date 2023-12-06

Pictures 0

Listing price <u>View report</u>

#### source: carcraft.co.uk

#### Entry 2

Date 2023-11-29

Pictures 3

Listing price <u>View report</u>







#### source: cargurus.co.uk

#### Entry 1

Date	2021-01-29
Pictures	0

Listing price <u>View report</u>

source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

GN15WYB report date: 2024-03-28

MOT expiry date	2025-01-22
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #8	2024-01-23 16:55
MOT test number	977118770113
Result	✓ Passed
Next expiry date	2025-01-22

MOT #7	2023-04-25 09:01
MOT test number	142138326057
Result	✓ Passed

MOT #6		2022-04-21 16:42
MOT test	number	938825916401
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3	(d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2	2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Slightly cracking	(5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5	5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Slightly cracking	g (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2022-04-21 14:15

**MOT test number** 161650147799

Result × Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing Slightly cracking (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Slightly cracking (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #4 2021-05-10 08:21

MOT test number 974818402012

**Result** ✓ Passed

**MOT #3** 2020-03-07 08:08

MOT test number 996962063716

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-02-12 11:36

**MOT test number** 548660389472

CarCheck.co.uk page 4/12



report date: 2024-03-28

**MOT #1** 2018-03-07 15:25

**MOT test number** 863382063355

**Result** ✓ Passed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

CarCheck.co.uk page 5/12



GN15WYB report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	بمرحاء المانحا
UWNEr	nistarv
OWILL	THISCOLY

o mile mesery		
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
**************************************		
THE PROPERTY OF THE PROPERTY O		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	OK SIE	
Plate since		
Current registration	UK WEST	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



**GN15WYB** report date: 2024-03-28

## Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-09
Last registration	2024-01-23
Complete history	See info



2015-03-09	29 mi
2018-03-07	20.303 mi
2019-02-12	22.605 mi
2020-03-07	24.797 mi
	11.777 es
2021-05-10	25.607 mi
	11.777 es
	2018-03-07 2019-02-12 2020-03-07

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

# Additional information

Fuel tank capacity	37 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 1121042