



**BV520FM**

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 LWB H/R P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

<b>MOT #21</b>	2020-03-04 10:42
<b>MOT test number</b>	350132377308
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-03-03
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #20</b>	2019-01-29 16:53
<b>MOT test number</b>	609834639949
<b>Result</b>	✓ Passed

<b>MOT #19</b>	2018-02-26 16:27
<b>MOT test number</b>	146036360210
<b>Result</b>	✓ Passed

<b>MOT #18</b>	2017-02-07 14:04
<b>MOT test number</b>	293991372838
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Brake pipe slightly corroded (3.6.B.2c)

<b>MOT #17</b>	2016-01-07 12:10
<b>MOT test number</b>	253253644336
<b>Result</b>	✓ Passed

**MOT #16** 2016-01-07 10:42**MOT test number** 795407965064**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Horn not working (1.6.2a)**Fail** Offside Rear Stop lamp not working (1.2.1b)**MOT #15** 2015-01-28 15:52**MOT test number** 239328625042**Result** ✓ Passed**Advice** Vehicle structure has slight corrosion (6.1.A.1)**MOT #14** 2015-01-28 09:36**MOT test number** 459758725075**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Vehicle structure has slight corrosion (6.1.A.1)**MOT #13** 2014-01-22 09:40**MOT test number** 139082324031**Result** ✓ Passed**MOT #12** 2013-01-24 14:32**MOT test number** 899204323084**Result** ✓ Passed

**MOT #11** 2013-01-24 08:48**MOT test number** 106154023011**Result** ✗ Failed

- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #10** 2012-02-10 09:48**MOT test number** 277731442032**Result** ✓ Passed

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2012-02-10 09:48**MOT test number** 158021442449**Result** ✗ Failed

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2011-01-18 10:32**MOT test number** 367518311078**Result** ✓ Passed**MOT #7** 2010-01-20 09:54**MOT test number** 902170820063**Result** ✓ Passed

**MOT #6** 2009-02-26 09:17**MOT test number** 850717359076**Result** ✓ Passed**MOT #5** 2008-06-04 12:09**MOT test number** 391366658164**Result** ✓ Passed**MOT #4** 2008-06-02 11:28**MOT test number** 854984758121**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-07-05 16:41**MOT test number** 143436987135**Result** ✓ Passed**MOT #2** 2006-07-17 15:46**MOT test number** 880138596154**Result** ✓ Passed**MOT #1** 2005-07-20 16:27**MOT test number** 783821105205**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2002-09-01
Last registration	2020-03-04
Complete history	<a href="#">See info</a>



Registration #1	2002-09-01	20 mi
Registration #2	2005-07-20	40.018 mi
Registration #3	2006-07-17	51.857 mi
Registration #4	2007-07-05	64.228 mi
Registration #5	2008-06-02	76.795 mi
Registration #6	2008-06-04	76.795 mi
Registration #7	2009-02-26	86.184 mi
Registration #8	2010-01-20	97.312 mi
Registration #9	2011-01-18	110.653 mi
Registration #10	2012-02-10	122.011 mi
Registration #11	2013-01-24	128.232 mi
Registration #12	2014-01-24	134.453 mi
Registration #13	2015-01-24	140.674 mi
Registration #14	2016-01-24	146.895 mi
Registration #15	2017-01-24	153.116 mi
Registration #16	2018-01-24	159.337 mi
Registration #17	2019-01-24	165.558 mi
Registration #18	2020-03-04	171.779 mi
Registration #19	2020-03-04	171.779 mi
Registration #20	2020-03-04	171.779 mi
Registration #21	2020-03-04	171.779 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Engine number	1K58608