






report date: 2024-03-29

General information

| Make | RENAULT |
|---------------------|---------------------------------------|
| Model | SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI |
| Colour | Red |
| Year of manufacture | 2011 |
| Top speed | 112 mph |
| 0 - 100 km/h | 12.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 78 kW / 106 HP / 110 BHP |
|-------------------------|--------------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.461 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-19

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-09-19 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 3 |

| MOT #12 | | 2023-09-20 14:12 |
|---|---|------------------|
| MOT test | number | 124151305550 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-09-19 |
| Advice Rear Direction indicator slightly discoloured Both sides. (4.4.3 (a)) | | |
| Advice Front Tyre worn close to legal limit/worn on edge Both front tyres worn on inner edge. (5.2.3 (e)) | | |
| Advice | Offside Front Radiator support damaged on underside of vehicle. | |

| ИОТ #11 | | 2023-09-20 14:12 |
|---|--|------------------|
| MOT test number | | 106552678482 |
| Result | | X Failed |
| Pass with rectification | Nearside Rear Stop lamp(s) not working (4.3.1 | (a) (ii)) |
| Advice Rear Direction indicator slightly discoloured Both sides. (4.4.3 (a)) | | |
| Advice Front Tyre worn close to legal limit/worn on edge Both front tyres worn on inner edge. (5.2.3 (e)) | | |
| Advice Offside Front Radiator support damaged on underside of vehicle. | | |
| Pass with rectification | Offside Rear Stop lamp(s) not working (4.3.1 (| a) (ii)) |

CarCheck.co.uk page 3/12



MOT #10 2022-05-31 08:45

MOT test number 390272240940

Result ✓ Passed

Advice Offside Front aluminium crossbar underneath vehicle very badly distorted and pulled out of front panel, strongly advise to get repaired asap

Advice Offside Front Oil leak

MOT #9 2021-06-16 09:48

MOT test number 429606882434

Result ✓ Passed

MOT #8 2020-05-22 14:22

MOT test number 896747190377

Result
✓ Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Oil leak, but not excessive Engine (8.4.1 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Sub-frame damaged but not seriously weakened (5.3.3 (b) (i))

MOT #7 2019-05-22 09:38

MOT test number 199632104645

Result ✓ Passed

MOT #6 2018-06-13 09:23

MOT test number 923150815950

Result ✓ Passed

MOT #5 2017-06-14 09:02

MOT test number 440687486539

Result

Passed

CarCheck.co.uk page 4/12



| MOT #4 | 2016-06-15 10:39 |
|---|------------------|
| MOT test number | 910465573440 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2015-06-26 12:23 |
| MOT test number | 267047575465 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2015-06-26 11:33 |
| MOT test number | 558427575178 |
| Result | × Failed |
| Fail Offside Stop lamp not working (1.2.1b) | |

| MOT #1 | 2014-05-30 09:40 |
|-----------------|------------------|
| MOT test number | 579300454171 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 19 September 2024

| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 19 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e mier metery | |
|---|-------------|
| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
| | |
| manus . | |
| | |
| *************************************** | |
| | |
| manus . | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| | |
| Current registration | NK SIE |
| Plate since | |
| Current registration | NK SIK |
| Plate since | |
| | More info > |
| | |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2011-06-23 |
| Last registration | 2023-09-20 |
| Complete history | See info |



| Registration #1 | 2011-06-23 | 18 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-05-30 | 16.652 mi |
| Registration #3 | 2015-06-26 | 20.554 mi |
| Registration #4 | 2015-06-26 | 20.555 mi |
| Registration #5 | 2016-06-15 | 22.525 mi |
| Registration #6 | 2017-06-14 | 23.757 mi |
| Registration #7 | 2018-06-13 | 25.190 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | D.777 es |
| Registration #13 | | 11.777 es |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| 50566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1486 mm |
|---------------------|---------|
| Height | 1637 mm |
| Length | 4344 mm |
| Wheel base | 2703 mm |
| Kerb weight | 1385 kg |
| Max. allowed weight | 1944 kg |

Additional information

| Fuel tank capacity | 60 I | |
|-----------------------------------|------------------|----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 pag | je 12/12 |

Number of axles 2

Engine number D246598