





General information

Make	NISSAN
Model	NV200 DCI E
Colour	White
Year of manufacture	2011
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP	0 < 101 A
Max. torque	200 Nm at 1.750 rpm	101 - 120 B
Engine capacity	1.461 cc	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185
Consumption city	49.6 mpg	186 - 225 K
Consumption extra urban	58.9 mpg	225+ L
Consumption combined	55.4 mpg	





Internet history

Entry 1	
Date	

2021-08-15

43

Listing price

Pictures

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-08
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	12
Total items failed	13

MOT #15	2023-09-06 14:43
MOT test number	302686435098
Result	Passed
Next expiry date	2024-09-08
Minor Front Headlamp lens slightly defective both (4.1.1 (b) (i))	
Advice Rear Registration plate insecure but not likely to fall off (0.1 (a))	

MOT #14	2023-09-05 14:02
MOT test number	301095302331
Result	🗙 Failed
Minor Front Headlamp lens slightly defective both (4.1.1 (b) (i))	
Advice Rear Registration plate insecure but not likely to fall off (0.1 (a))
Advice Offside Front Suspension arm pin or bush worn but not resultin (i))	ng in excessive movement (5.3.4 (a)
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2)	.3 (e))
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Fail Offside Front Suspension arm pin or bush excessively worn rear bush	ush (5.3.4 (a) (i))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	





MOT #13	2022-09-09 15:47
MOT test number	884994218777
Result	✓ Passed
MinorOffside Obligatory mirror slightly damaged on limit, advise new (3.3 (b) (i))AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12 2022-09-09 09:49 **MOT test number** 589331254080 Result X Failed Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii)) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Minor Offside Obligatory mirror slightly damaged on limit, advise new (3.3 (b) (i))

MOT #11	2021-08-12 10:50
MOT test number	185325195771
Result	✓ Passed

MOT #10	2021-08-11 10:02	
MOT test number	202143550455	
Result	🗙 Failed	
Fail Offside Front Service brake excessively binding (1.2.1 (f))		
Fail Offside Front Lower Suspension arm pin or bush excessively worn Wishbone inner bush marked with chalk (5.3.4 (a) (i))		
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))		
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in Wishbone inner bush marked with chalk (5.3.4 (a) (i))	excessive movement	





МОТ #9	2020-09-05 12:24
MOT test number	814208378025
Result	✓ Passed
MOT #8	2019-09-28 09:32
MOT test number	379182663166
Result	✓ Passed
MOT #7	2019-09-28 09:32
MOT test number	746618351881
Result	🗙 Failed

Pass with rectification

Headlamp aim too low (4.1.2 (a))

МОТ #6	2018-11-10 10:07
MOT test number	135225256076
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting (a) (i))	in excessive movement (5.3.4

MOT #5	2017-11-11 09:22
MOT test number	845389655317
Result	✓ Passed
МОТ #4	2016-11-19 09:42
MOT test number	855716216988
Result	✓ Passed

MOT #3	2015-11-21 09:34
MOT test number	929285611852
Result	✓ Passed





MOT #2		2014-11-15 11:00
MOT test number		957279214372
Result		✓ Passed
MOT #1		2014-11-15 11:00
MOT test number		146929514335
Result		🗙 Failed
Pass with rectification	Rear Stop lamp not working (1.2.1b)	



Tax & MOT check

✓ Taxed	√ МОТ
Tax due: 1 August 2024	Expires: 8 September 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	8 September 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-25
Last registration	2023-09-06
Complete history	See info



Registration #1	2011-11-25	23 mi
Registration #2	2014-11-15	25.700 mi
Registration #3	2015-11-21	35.420 mi
Registration #4	2016-11-19	44.794 mi
Registration #5	2017-11-11	51.522 mi
Registration #6	2018-11-10	56.746 mi
Registration #7	2019-09-28	60.880 mi
Registration #8	2019-09-28	60.880 mi
-		
Registration #9		11.777 mi
		10.000 est
Registration #9		00.000 est 00.000 est 00.000 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		00.000 460 00.000 460 00.000 460 00.000 460 00.000 460
Registration #9 Registration #10 Registration #11 Registration #12		00.000 460 01.000 460 00.000 460 00.000 460 00.000 460 00.000 460
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13		00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2011 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1261 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	016960