



report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-01
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #22	2023-10-17 12:12
MOT test number	733450230470
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2023-10-17 12:12
MOT test number	164201088932
Result	✗ Failed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #20	2022-09-23 09:02
MOT test number	904205249296
Result	✓ Passed

MOT #19	2021-10-07 14:58
MOT test number	230984767031
Result	✓ Passed

MOT #18	2021-09-21 15:49
MOT test number	310182656282
Result	✗ Failed
MAJOR	Offside Rear All direction indicators adversely affected by the operation of another lamp (4.4.3 (b))
MAJOR	Rear Rear fog lamp not working (4.5.1 (a) (ii))
MAJOR	Nearside Rear All direction indicators adversely affected by the operation of another lamp (4.4.3 (b))

MOT #17	2021-01-11 15:46
MOT test number	941621622740
Result	✓ Passed

**MOT #16** 2021-01-09 15:46**MOT test number** 803733538116**Result** ✗ Failed**MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #15** 2019-12-19 09:54**MOT test number** 745254010420**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-12-19 15:14**MOT test number** 339370837366**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13** 2018-12-19 12:31**MOT test number** 572357760400**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #12** 2017-12-13 10:06**MOT test number** 400352651972**Result** ✓ Passed**MOT #11** 2017-01-10 14:28**MOT test number** 878793381703**Result** ✓ Passed**Advice** High level brake light inop**MOT #10** 2017-01-10 10:51**MOT test number** 166858127606**Result** ✗ Failed**Fail** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** High level brake light inop**Fail** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #9** 2015-12-08 13:31**MOT test number** 921876467563**Result** ✓ Passed**Advice** Offside rear tyre has cracks all around tyre tread**Advice** Under trays fitted**MOT #8** 2015-12-08 10:13**MOT test number** 740336656389**Result** ✗ Failed**Advice** Offside rear tyre has cracks all around tyre tread**Fail** Offside Rear Rear fog lamp has less than 50% of the light sources illuminating (1.3.2b)**Advice** Under trays fitted**MOT #7** 2014-12-12 10:05**MOT test number** 579866644317**Result** ✓ Passed**MOT #6** 2013-12-28 12:11**MOT test number** 758562763353**Result** ✓ Passed**MOT #5** 2013-01-07 11:47**MOT test number** 157617503096**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



MOT #4	2013-01-07 11:47
---------------	------------------

MOT test number	987677003023
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Stop lamp not working (1.2.1b)
--------------------------------	---

Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
---------------	---

MOT #3	2011-12-30 15:49
---------------	------------------

MOT test number	145484861393
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-05-09 12:19
---------------	------------------

MOT test number	379339021159
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-04-19 12:19
---------------	------------------

MOT test number	221029200411
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LT07LKV
Plate since	2019-03-28
Current registration	LT07LKV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-05-18
Last registration	2023-10-17
Complete history	See info



Registration #1	2007-05-18	7 mi
Registration #2	2010-04-19	14.665 mi
Registration #3	2011-05-09	20.496 mi
Registration #4	2011-12-30	23.938 mi
Registration #5	2013-01-07	33.172 mi
Registration #6	2013-12-28	40.914 mi
Registration #7	2014-12-12	46.114 mi
Registration #8	2015-12-08	51.519 mi
Registration #9	2015-12-08	51.519 mi
Registration #10	2017-01-10	57.933 mi
Registration #11	2017-01-10	57.933 mi
Registration #12	2017-12-13	63.428 mi
Registration #13	2019-05-20	65.377 mi
Registration #14	2019-05-20	65.377 mi
Registration #15	2019-05-20	65.377 mi
Registration #16	2019-05-20	65.377 mi
Registration #17	2019-05-20	65.377 mi
Registration #18	2019-05-20	65.377 mi
Registration #19	2019-05-20	65.377 mi
Registration #20	2019-05-20	65.377 mi
Registration #21	2019-05-20	65.377 mi
Registration #22	2019-05-20	65.377 mi
Registration #23	2019-05-20	65.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7E54776