



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S V50
Colour	Grey
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.2 mpg





Internet history

Entry 2

Date	2021-08-09
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-07
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #15</b>	2021-08-09 13:53
<b>MOT test number</b>	661444561870
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-08-08
<b>Minor</b>	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #14</b>	2020-09-22 11:41
<b>MOT test number</b>	632763055489
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2019-06-14 08:00
<b>MOT test number</b>	406822181790
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
<b>Advice</b>	Offside front orange position lamp inoperative
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

<b>MOT #12</b>	2018-06-14 16:26
<b>MOT test number</b>	808951866751
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear tyres perished
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11** 2018-06-14 08:15**MOT test number** 742105547427**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear tyres perished**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2017-06-28 16:03**MOT test number** 118712667935**Result** ✓ Passed**Advice** Rear parking (secondary) brake grabbing slightly (3.7.B.6b)**MOT #9** 2017-06-28 12:59**MOT test number** 818987817616**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Side repeater not working (1.4.A.2c)**Fail** Offside Front Body has a sharp edge caused by damage side mirror cover (6.1.C.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-06-17 08:52**MOT test number** 371024123058**Result** ✓ Passed**Advice** Nearside front tyre low

**MOT #7** 2015-06-01 13:11**MOT test number** 548092455154**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-06-16 11:37**MOT test number** 797857564176**Result** ✓ Passed**MOT #5** 2013-06-06 10:38**MOT test number** 608807253115**Result** ✓ Passed**MOT #4** 2012-06-07 10:59**MOT test number** 958709352141**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2011-06-15 10:15**MOT test number** 416306661115**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2010-06-17 11:05**MOT test number** 272858960188**Result** ✓ Passed**MOT #1** 2009-06-08 12:04**MOT test number** 212629859462**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-30
Last registration	2021-08-09
Complete history	<a href="#">See info</a>



Registration #1	2006-06-30	18 mi
Registration #2	2009-06-08	19.762 mi
Registration #3	2010-06-17	25.236 mi
Registration #4	2011-06-15	30.629 mi
Registration #5	2012-06-07	37.081 mi
Registration #6	2013-06-06	44.057 mi
Registration #7	2014-06-16	51.983 mi
Registration #8	2015-06-01	59.227 mi
Registration #9	2016-06-17	68.276 mi
Registration #10	2016-06-17	75.277 mi
Registration #11	2016-06-17	82.277 mi
Registration #12	2016-06-17	89.277 mi
Registration #13	2016-06-17	96.277 mi
Registration #14	2016-06-17	103.277 mi
Registration #15	2016-06-17	110.277 mi
Registration #16	2016-06-17	117.277 mi
Registration #17	2016-06-17	124.277 mi
Registration #18	2016-06-17	131.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4513 mm
Wheel base	2640 mm
Kerb weight	1306 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	59516