





General information

Make	HYUNDAI
Model	TUCSON GDI S CONNECT
Colour	Black
Year of manufacture	2018
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	132 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	157 g/km
CO2 label	G







Internet history

Entry 1

Date Pictures 2022-05-06

22

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	5

MOT #5	2023-07-03 07:53
MOT test number	381178956071
Result	✓ Passed
Next expiry date	2024-07-04
Advice Rear upper spoiler insecure	
Advice Offside Front Inner Driver's door hinge deteriorated but the door can still be readily opened and closed door hinge has play (6.2.3 (c) (i))	
Advice Offside rear body damage taped up	

MOT #4	2023-06-30 10:26
MOT test number	169517551130
Result	🗙 Failed
Fail Offside Rear Outer Bumper damaged and likely to cause injury when grazed or contacted bumper	

near light unit damage sharp edges (6.1.4 (a) (i))

Advice Rear upper spoiler insecure

Advice Offside Front Inner Driver's door hinge deteriorated but the door can still be readily opened and closed door hinge has play (6.2.3 (c) (i))

МОТ #3	2022-07-05 15:40
MOT test number	740449335708
Result	✓ Passed



BT68GUK
report date: 2024-03-28

MOT #2		2021-11-23 15:23
MOT test n	umber	624188884339
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Hand brake travel high	
MOT #1		2021-11-22 14:21
MOT test n	number	765441441192
Result		🗙 Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge tyre at 2mm (5.2.3 ((e))
Fail Off	fside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing heavy cracking (5.2	.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Hand brake travel high

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 January 2025	Expires: 4 July 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Record contribution	
Carrent registration	







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-12-19
Last registration	2023-07-03
Complete history	<u>See info</u>



Registration #1	2018-12-19	13 mi
Registration #2	2021-11-22	26.638 mi
Registration #3	2021-11-23	26.641 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.227 mi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	2065 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1414 kg
Max. allowed weight	2030 kg
Additional information	
Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11