



report date: 2024-03-29

General information

Make	CITROEN
Model	C-CROSSER CODE
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	380 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-05
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #19** 2022-11-30 15:41**MOT test number** 726596512430**Result** ✓ Passed**Next expiry date** 2023-11-29

- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18 2021-11-04 10:33**MOT test number** 296218476247**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Spare tyre defective
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #17

2021-11-04 10:33

MOT test number

481042828506

Result

✗ Failed

Advice Spare tyre defective**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #16

2020-11-30 09:40

MOT test number

909068968580

Result

✓ Passed

MOT #15

2020-11-30 09:40

MOT test number

937962643294

Result

✗ Failed

Pass with rectification Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Pass with rectification** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #14

2019-05-08 13:44

MOT test number

538289872691

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13** 2018-05-29 11:44**MOT test number** 336252650150**Result** Passed**MOT #12** 2018-05-24 15:05**MOT test number** 892321682157**Result** Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Rear nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2017-09-11 15:13**MOT test number** 907188624775**Result** Passed**Advice** All ball joint boot covers perished

**MOT #10**

2017-09-11 08:23

MOT test number

375461331575

Result**✗ Failed****Fail** Nearside Front Outer Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Central Rear Statutory seat belt missing (5.1.1)**Fail** Offside Front Outer Track rod end ball joint has excessive play (2.2.B.1f)**Advice** All ball joint boot covers perished**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #9**

2016-10-03 13:22

MOT test number

761975334364

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Nearside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #8** 2016-09-30 10:32**MOT test number** 544618433095**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Nearside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)

MOT #7 2015-09-01 11:24**MOT test number** 537939892687**Result** ✓ Passed**MOT #6** 2014-09-26 12:16**MOT test number** 355169564471**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components

**MOT #5** 2013-10-01 08:54**MOT test number** 367284673237**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in o/s/r tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-10-01 08:54**MOT test number** 526004773279**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in o/s/r tyre**MOT #3** 2012-09-25 16:52**MOT test number** 698899262210**Result** ✓ Passed



MOT #2	2012-09-25 08:57
MOT test number	639539862261
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Parking brake lever has little reserve travel (3.1.6b)

MOT #1	2011-09-27 12:04
MOT test number	265330271236
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YG58MWP
Plate since	2019-03-29
Current registration	YG58MWP
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-30
Last registration	2022-11-30
Complete history	See info



Registration #1	2008-09-30	13 mi
Registration #2	2011-09-27	32.478 mi
Registration #3	2012-09-25	46.720 mi
Registration #4	2012-09-25	46.720 mi
Registration #5	2013-10-01	59.983 mi
Registration #6	2014-09-26	73.892 mi
Registration #7	2015-09-01	84.480 mi
Registration #8	2016-09-30	99.361 mi
Registration #9	2016-10-03	99.365 mi
Registration #10	2017-09-11	110.329 mi
Registration #11	2018-09-27	121.377 mi
Registration #12	2019-09-27	132.425 mi
Registration #13	2020-09-27	143.473 mi
Registration #14	2021-09-27	154.521 mi
Registration #15	2022-09-27	165.569 mi
Registration #16	2023-09-27	176.617 mi
Registration #17	2024-09-27	187.665 mi
Registration #18	2025-09-27	198.713 mi
Registration #19	2026-09-27	209.761 mi
Registration #20	2027-09-27	220.809 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ554007100