



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	Red
Year of manufacture	2011
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	61.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-18
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	22
Total items failed	12

MOT #16	2023-10-17 16:01
MOT test number	334934460479
Result	✓ Passed
Next expiry date	2024-10-27
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2022-10-17 14:02
MOT test number	950849596764
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Play in steering rack inner joint(s) both
Advice	Offside Front Power steering component has slight seepage from a component rack head (2.1.5 (a))

MOT #14	2021-10-28 10:23
MOT test number	398564956603
Result	✓ Passed

**MOT #13**

2021-10-27 14:26

MOT test number

844330479842

Result**✗ Failed****Fail**

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Hole in tyre has been plugged with temporary repair compound (5.2.3 (d) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge Inner edge wear (5.2.3 (e))

MOT #12

2021-05-11 10:35

MOT test number

837170920621

Result**✓ Passed****Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2021-05-10 11:04

MOT test number

277121155078

Result**✗ Failed**

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Rear fog lamp adversely affected by the operation of another lamp (4.5.4 (b))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #10

2020-05-19 11:31

MOT test number

376138863430

Result**✓ Passed**

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Direction indicator slightly affected by the operation of another lamp (4.4.3 (b))

**MOT #9** 2019-07-22 16:12**MOT test number** 233807067914**Result** ✓ Passed**MOT #8** 2019-07-19 16:20**MOT test number** 383941014597**Result** ✗ Failed**Fail** Rear Sub-frame fractured (5.3.3 (b) (ii))**MOT #7** 2018-08-03 13:23**MOT test number** 924035357716**Result** ✓ Passed**MOT #6** 2018-08-03 09:53**MOT test number** 702805905428**Result** ✗ Failed**Fail** Nearside Rear Position lamp not working (4.2.1 (a))**MOT #5** 2017-08-14 13:17**MOT test number** 169208154006**Result** ✓ Passed**Advice** NS RACK GAITER TWISTED**MOT #4** 2016-08-19 15:32**MOT test number** 427683129530**Result** ✓ Passed**MOT #3** 2015-08-18 00:00**MOT test number** 475940550647**Result** ✓ Passed



MOT #2	2014-08-19 16:46
MOT test number	678851734212
Result	✓ Passed

MOT #1	2013-09-04 15:24
MOT test number	187277343242
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Nail in offside rear tyre
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
27 October 2024

Tax status		Valid until 1 May
Days left		367
MOT expiry date		27 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KN11YTE
Plate since	2024-03-28
Current registration	KN11YTE
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-04-26
Last registration	2023-10-17
Complete history	See info



Registration #1	2011-04-26	19 mi
Registration #2	2013-09-04	13.878 mi
Registration #3	2014-08-19	21.388 mi
Registration #4	2015-08-18	28.799 mi
Registration #5	2016-08-19	34.820 mi
Registration #6	2017-08-14	39.936 mi
Registration #7	2018-08-03	44.505 mi
Registration #8	2018-08-03	44.505 mi
Registration #9	2019-07-19	49.629 mi
Registration #10	2019-07-19	55.753 mi
Registration #11	2019-07-19	61.877 mi
Registration #12	2019-07-19	67.999 mi
Registration #13	2019-07-19	74.121 mi
Registration #14	2019-07-19	80.243 mi
Registration #15	2019-07-19	86.365 mi
Registration #16	2019-07-19	92.487 mi
Registration #17	2019-07-19	98.609 mi
Registration #18	2019-07-19	104.731 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1321 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982964254