



SCI2VRF

report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	-
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	0
Listing price	View report

source: autoonline.co.uk

**MOT history**

MOT #12	2022-09-16 11:01
MOT test number	743219775795
Result	✓ Passed
Next expiry date	2023-09-19
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-09-20 13:24
MOT test number	905973567782
Result	✓ Passed

MOT #10	2021-09-16 17:04
MOT test number	938922783014
Result	✗ Failed
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))



MOT #9

2020-02-13 15:28

MOT test number

979404929094

Result

✓ Passed

- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Items removed from driver's view prior to test
- Advice

Sump corroded
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge tyre on 2mm (5.2.3 (e))
- Advice

Back box outer casing rotten

**MOT #8** 2020-02-13 11:52**MOT test number** 308366129550**Result** ✗ Failed

- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Sump corroded
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Items removed from driver's view prior to test
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Back box outer casing rotten
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre on 2mm (5.2.3 (e))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7 2019-02-22 09:56**MOT test number** 662814062258**Result** ✓ Passed

- Minor** Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))

MOT #6 2019-02-19 15:48**MOT test number** 672491403080**Result** ✗ Failed

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))



MOT #5	2018-02-23 11:19
MOT test number	881972003635
Result	✓ Passed
MOT #4	2017-06-23 13:24
MOT test number	873052347289
Result	✓ Passed
MOT #3	2017-06-23 11:03
MOT test number	614753538484
Result	✗ Failed
<div><div>Fail</div>Offside Front coil spring broken (2.4.C.1a)</div>	
MOT #2	2016-06-24 14:36
MOT test number	513319850614
Result	✓ Passed
MOT #1	2015-07-01 10:52
MOT test number	138822585112
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-29
Last registration	2022-09-16
Complete history	See info



Registration #1	2012-06-29	6 mi
Registration #2	2015-07-01	12.724 mi
Registration #3	2016-06-24	16.205 mi
Registration #4	2017-06-23	19.946 mi
Registration #5	2017-06-23	19.946 mi
Registration #6	2018-02-23	22.557 mi
Registration #7	2019-02-19	27.415 mi
Registration #8	2019-09-20	28.277 mi
Registration #9	2019-09-20	28.277 mi
Registration #10	2019-09-20	28.277 mi
Registration #11	2019-09-20	28.277 mi
Registration #12	2019-09-20	28.277 mi
Registration #13	2019-09-20	28.277 mi
Registration #14	2019-09-20	28.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	6913671