



TOYOTA

FE060CH

report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Grey
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: autoonline.co.uk

**MOT history****MOT #20** 2022-09-30 10:04**MOT test number** 276018287959**Result** ✗ Failed**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**Fail** Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting under body Sill area front and back both side excessively corroded (6.2.2 (d) (i))**Fail** Front Tyre has ply or cords exposed both side (5.2.3 (d) (ii))**Advice** Rear axle and components are corroded**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Coil spring corroded both side (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front subframe and components are corroded**Advice** Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both side (4.1.4 (b))**MOT #19** 2021-03-10 16:01**MOT test number** 435935864551**Result** ✓ Passed**MOT #18** 2019-05-07 13:47**MOT test number** 905359008924**Result** ✓ Passed**MOT #17** 2018-09-28 11:41**MOT test number** 677546932755**Result** ✓ Passed

**MOT #16** 2018-02-22 10:39**MOT test number** 942145618121**Result** ✓ Passed**Advice** Under trays fitted to vehicle**MOT #15** 2017-02-27 13:23**MOT test number** 630802228357**Result** ✓ Passed**Advice** Brake hose has slight corrosion to ferrules all (3.6.B.4e)**MOT #14** 2017-02-27 13:23**MOT test number** 945997428320**Result** ✗ Failed**Advice** Brake hose has slight corrosion to ferrules all (3.6.B.4e)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #13** 2016-09-21 11:49**MOT test number** 673458458125**Result** ✓ Passed**MOT #12** 2016-09-20 15:47**MOT test number** 860447037056**Result** ✗ Failed**Fail** Nearside Rear brake caliper securing device missing Bolts missing (3.5.1j)**Fail** Brake performance not tested N/s rear caliper bolts missing (3.7.A.1)

**MOT #11** 2016-03-11 15:44**MOT test number** 702380230537**Result** ✓ Passed**Advice** Rear disc's corroded**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #10** 2016-03-10 09:27**MOT test number** 776371614772**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Rear disc's corroded**MOT #9** 2015-03-03 13:45**MOT test number** 945002065092**Result** ✓ Passed**MOT #8** 2015-03-03 08:57**MOT test number** 228862565002**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2014-03-10 09:52**MOT test number** 776929964038**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #6	2013-03-12 09:34
---------------	------------------

MOT test number	115721473469
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2012-03-13 12:11
---------------	------------------

MOT test number	675733772072
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tie bar/rod ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
---------------	---

Notice	Under-trays fitted obscuring some underside components
---------------	--

Advice	Nearside Front Tie bar/rod ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
---------------	--

Notice	Engine covers fitted obscuring some components in the engine bay
---------------	--

MOT #4	2011-03-14 10:01
---------------	------------------

MOT test number	559543171095
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2010-08-23 16:24
---------------	------------------

MOT test number	500405530206
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-03-08 11:40
---------------	------------------

MOT test number	224827660090
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2009-03-16 08:55
---------------	------------------

MOT test number	731045979025
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-15
Last registration	2022-09-30
Complete history	See info



Registration #1	2006-03-15	6 mi
Registration #2	2009-03-16	22.942 mi
Registration #3	2010-03-08	32.209 mi
Registration #4	2010-08-23	35.104 mi
Registration #5	2011-03-14	40.741 mi
Registration #6	2012-03-13	52.132 mi
Registration #7	2013-03-12	62.838 mi
Registration #8	2014-03-10	75.222 mi
Registration #9	2015-03-03	85.837 mi
Registration #10	2015-03-03	85.837 mi
Registration #11	2016-03-10	95.640 mi
Registration #12	2016-03-10	95.640 mi
Registration #13	2016-03-10	95.640 mi
Registration #14	2016-03-10	95.640 mi
Registration #15	2016-03-10	95.640 mi
Registration #16	2016-03-10	95.640 mi
Registration #17	2016-03-10	95.640 mi
Registration #18	2016-03-10	95.640 mi
Registration #19	2016-03-10	95.640 mi
Registration #20	2016-03-10	95.640 mi
Registration #21	2016-03-10	95.640 mi
Registration #22	2016-03-10	95.640 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1585 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0082158