



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 230 KOMPRESSOR SPECIAL EDITION
Colour	Silver
Year of manufacture	2004
Top speed	147 mph
0 - 60 mph	7.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Engine capacity	2.295 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	39.8 mpg
Consumption combined	28.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1	
Date	2021-09-24
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-09
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	54
Total items failed	10

MOT #23	2023-10-10 15:40
MOT test number	552558586517
Result	✓ Passed
Next expiry date	2024-10-09
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))
Advice	Play in steering rack inner joint(s)
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #22**

2023-10-03 15:48

MOT test number

696705344107

Result**✗ Failed****MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Rear Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Play in steering rack inner joint(s)**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #21**

2022-10-05 16:16

MOT test number

208602271365

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #20** 2022-10-05 10:52**MOT test number** 298480556522**Result** ✗ Failed

- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #19 2021-10-06 09:15**MOT test number** 570707857813**Result** ✓ Passed**MOT #18** 2021-06-24 14:02**MOT test number** 346648390236**Result** ✓ Passed**MOT #17** 2020-06-11 08:12**MOT test number** 528611504846**Result** ✓ Passed

**MOT #16**

2019-03-28 15:33

MOT test number

321980876879

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #15**

2019-03-28 15:32

MOT test number

939273118771

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #14**

2018-04-27 11:58

MOT test number

458975087157

Result

✓ Passed

Advice Both rear coil springs rusty**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Exhaust rusty

**MOT #13** 2018-04-24 14:28**MOT test number** 494809879130**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Exhaust rusty**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Headlamp aim too low (1.8)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Both rear coil springs rusty**MOT #12** 2017-03-25 08:45**MOT test number** 414123349609**Result** ✓ Passed**MOT #11** 2016-03-08 10:10**MOT test number** 743668947273**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2016-03-08 10:10**MOT test number** 504465528155**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #9** 2014-08-14 16:04**MOT test number** 867736324239**Result** ✓ Passed

- Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)
- Notice** Under-trays fitted obscuring some underside components

MOT #8 2013-08-17 08:45**MOT test number** 819159223235**Result** ✓ Passed

- Advice** Offside Front Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Front Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2012-08-17 16:42**MOT test number** 739500232201**Result** ✓ Passed**MOT #6** 2011-08-20 12:03**MOT test number** 648022231237**Result** ✓ Passed**MOT #5** 2010-08-25 08:52**MOT test number** 510397330281**Result** ✓ Passed

- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



MOT #4	2009-08-29 08:50
MOT test number	330321549237
Result	✓ Passed
MOT #3	2008-08-30 08:26
MOT test number	851733648241
Result	✓ Passed
MOT #2	2007-08-31 14:55
MOT test number	203033547252
Result	✓ Passed
MOT #1	2007-08-31 11:53
MOT test number	912403247264
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
9 October 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 LM04FKR
Plate since	2019-06-29
Current registration	 LM04FKR
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-06-29
Last registration	2023-10-10
Complete history	See info



Registration #1	2004-06-29	29 mi
Registration #2	2007-08-31	28.551 mi
Registration #3	2007-08-31	28.553 mi
Registration #4	2008-08-30	35.923 mi
Registration #5	2009-08-29	43.908 mi
Registration #6	2010-08-25	50.365 mi
Registration #7	2011-08-20	57.589 mi
Registration #8	2012-08-17	63.295 mi
Registration #9	2013-08-17	68.852 mi
Registration #10	2014-08-14	73.409 mi
Registration #11	2016-03-08	77.558 mi
Registration #12	2016-03-08	77.558 mi
Registration #13	2017-03-25	80.125 mi
Registration #14	2018-03-25	80.125 mi
Registration #15	2018-03-25	80.125 mi
Registration #16	2018-03-25	80.125 mi
Registration #17	2018-03-25	80.125 mi
Registration #18	2018-03-25	80.125 mi
Registration #19	2018-03-25	80.125 mi
Registration #20	2018-03-25	80.125 mi
Registration #21	2018-03-25	80.125 mi
Registration #22	2018-03-25	80.125 mi
Registration #23	2018-03-25	80.125 mi
Registration #24	2018-03-25	80.125 mi
Registration #25	2018-03-25	80.125 mi



Dimensions & weight

Width	1715 mm
Height	1281 mm
Length	4010 mm
Wheel base	2400 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11198340087137